

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008774/EVF3E2

Date: 02/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700085681
Claimant Vehicle No : FQ6299E	Insured Vehicle No :	SJW6686S
Date of Loss: 27/07/2018	Nature of Claim:	TP Claim No: 9725888298SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FQ6299E	Engine No:	HIDDEN
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	ZMC239065
Reg. Date:	(Man. Year:)	Odometer:	65329 km
Colour:	Red		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80-18	Rear Tyre Size:	70/80-18
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/08/2020	Inspected At:	#01-436 Block 3007 Ubi Road 1
Date Inspected:	21/08/2020		Repairer : A.S. Phoon Pte Ltd
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F	
2	2		*FRONT FORK ASSY	Bent	0.00 F	*- F	
3	1		*FRONT HEADLAMP FAIRING	Broken	0.00 F	*- F	
4	1		*FRONT WING MIRROR	Cut	0.00 F	*- F	
5	1		*METER ASSY	Cut	0.00 F	*- F	
6	2		*HANDLE BAR	Bent	0.00 F	*- F	
7	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F	
8	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F	
9	1		*CLUTCH LEVER	Broken	0.00 F	*- F	
10	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F	
11	2		*SIDE FAIRING	Broken	0.00 F	*- F	
12	1		*SEAT ASSY	Torn	0.00 F	*- F	
13	1		*FOOT BRAKE	Bent	0.00 F	*- F	
14	1		*FRONT FOOT REST	Broken	0.00 F	*- F	
15	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F	
16	1		*EMBLEM	Necessary	0.00 F	*- F	
17	1		*STICKER	Necessary	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >