

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008779/ARS3Q2
Date: 14/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800096038
Claimant Vehicle No :	SKK1447A	Insured Vehicle No :	SBT8982J
Date of Loss:	15/08/2020	Nature of Claim:	TP
		Claim No:	3366163096SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK1447A	Engine No:	A25A5141492
Make & Model:	TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) LUXURY (A)	Chassis No:	JTHB11B1702008200
Reg. Date:	16/12/2019 (Man. Year: 2019)	Odometer:	12306 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,608.75	5,600.15	18,008.60	76.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,635.00	1,270.00	2,365.00	65.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,243.75	6,870.15	20,373.60	74.78
Approved Total (Overridden) (S\$)		5,500.00		

(S\$)	27,243.75	5,500.00	21,743.75	79.81
+ GST 7.00/7.00% (S\$)	1,907.06	385.00	1,522.06	79.81
Nett Amount (S\$)	29,150.81	5,885.00	23,265.81	79.81
+ Car Rental (5.0 x S\$140.00/day) (S\$)		700.00		
(S\$)		6,585.00		
Liabe Amount (50.00%) (S\$)		3,292.50		
Global Sum Settlement (S\$)		3,290.00		

INSPECTION

Date of Assignment: 21/08/2020

Date Inspected: 21/08/2020

Inspected At:

SK Automobile Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
 Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	1,617.70 FL	*1,617.70 FL
2	1		*FRONT FENDER TOP GARNISH RH	Not Necessary	128.30 FL	*- FL
3	1		*FRONT FENDER TOP RUBBER SEAL RH	Not Necessary	100.20 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	479.90 FL	*- FL
5	1		*FRONT FENDER BRACKET RH	Not Necessary	55.80 FL	*- FL
6	1		*FRONT HEADLAMP RH	Not Necessary	10,273.70 FL	*- FL
7	1		*FRONT HEADLAMP LED BALLAST RH	Not Necessary	1,328.60 FL	*- FL
8	1		*FRONT HEADLAMP NOZZLE RH	Not Necessary	686.90 FL	*- FL
9	1		*FRONT HEADLAMP NOZZLE BRACKET RH (STICK ON)	Not Necessary	30.50 FL	*- FL
10	1		*FRONT HEADLAMP NOZZLE HOSE RH	Not Necessary	70.40 FL	*- FL
11	1		*FRONT BUMPER	Deformed	1,046.60 FL	*1,046.60 FL
12	1		*FRONT BUMPER FOG LAMP COVER WITH CHROME MOULDING RH	Not Necessary	223.90 FL	*- FL
13	2		*FRONT BUMPER PARKING SENSOR ASSY	Not Necessary	1,071.60 FL	*- FL
14	4		*FRONT BUMPER PARKING HOLDER (STICK ON)	Necessary	82.80 FL	*82.80 FL
15	1		*SET FRONT BUMPER PARKING WIRE HARNESS	Not Necessary	143.60 FL	*- FL
16	1		*FRONT BUMPER TOP RUBBER SEAL (STICK ON)	Not Necessary	93.50 FL	*- FL
17	1		*FRONT BUMPER NOZZLE COVER RH	Not Necessary	155.40 FL	*- FL
18	2		*FRONT BUMPER SIDE RETAINER LH/RH	Damaged	86.40 FL	*86.40 FL
19	1		*FRONT BUMPER INNER SPONGE	Not Necessary	112.10 FL	*- FL
20	1		*FRONT BUMPER REINFORCEMENT SUPPORT FRAME	Not Necessary	503.70 FL	*- FL
21	1		*FRONT BUMPER INNER LOWER SUPPORT FRAME	Not Necessary	281.60 FL	*- FL
22	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	535.60 FL	*- FL
23	1		*FRONT SUSPENSION KNUCKLE ARM RH	Not Necessary	734.80 FL	*- FL
24	1		*FRONT SUSPENSION KNUCKLE ARM BEARING RH	Not Necessary	611.70 FL	*- FL
25	1		*FRONT SUSPENSION LOWER ARM RH	Not Necessary	760.60 FL	*- FL
26	1		*FRONT SUSPENSION LOWER BALL JOINT RH	Not Necessary	264.40 FL	*- FL
27	1		*FRONT 18 SPORT RIM RH	Cut	3,533.31 FS	*3,000.00 FS
28	1		*WASHER TANK	Not Necessary	273.70 FL	*- FL
29	1		*WASHER TANK NECK	Not Necessary	107.60 FL	*- FL
30	1		*FRONT FENDER TOP GARNISH CLIPS SET RH	Not Necessary	60.00 FS	*- FS
31	1		*FRONT FENDER INNER SHIELD CLIPS SET RH	Not Necessary	100.00 FS	*- FS
32	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
33	1		*SET FRONT BUMPER LOWER UNDER COVER CLIPS	Not Necessary	80.00 FS	*- FS
34	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	25,794.91	5,883.50
					- List Item Discount on L Items 10.00/10.00% (S\$)	2,186.16	283.35
					Total Parts (S\$)	23,608.75	5,600.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,250.00	500.00
2	TO SPRAY PAINTNG ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,000.00	500.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	105.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR WITH DISTANCE SETTING	New	120.00	60.00
6	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	New	480.00	0.00
7	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	140.00	80.00
8	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	380.00	100.00
9	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$\$)			3,635.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >