Page 1 of 5 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008780/UQF3E2

Date: 24/09/2020

REFERENCE

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSN30646219011

Claimant Vehicle FBN1596T

Insured Vehicle No:

SLT5300D

Date of Loss: 10/08/2020 Nature of ΤP Claim:

Claim

Odometer:

SNM20D202827/C02/LEWLC No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN1596T**

Make & Model: YAMAHA NMAX155, 155cc Reg. Date: 24/07/2018 (Man. Year: 2018)

G3H6E0009524 Engine No: Chassis No: MH3SG431000007369

33671 km

Colour: White

Engine Capacity: 155 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

130-70-13 Front Tyre Size: 110-70-13 Rear Tyre Size: Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Rear Right Side: Front Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,256.00	915.40	340.60	27.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,219.00	755.00	1,464.00	65.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,475.00	1,670.40	1,804.60	51.93
+ GST 7.00/7.00% (S\$)	243.25	116.93	126.32	51.93
Nett Amount (S\$)	3,718.25	1,787.33	1,930.92	51.93

INSPECTION

Date of Assignment: 20/08/2020

Date Inspected: 21/08/2020 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)

> No. 6 Defu Lane 4 Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 24/9/2020

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Part Source: (Last Synchronised: 24 Sep 2020)

Parts: N/A YAMAHA NMAX155 155cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN1596T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR HANDLE	Serviceable	33.00 F	*- FL
2	1		*BELLY PAN	Cut	34.00 F	*34.00 FL
3	1		*BOARD FOOTREST LH	Cut	52.00 F	*52.00 FL
4	1		*BOARD FOOTREST RH	Deformed	52.00 F	*52.00 FL
5	1		*BOX FILTER AIR OUTER	Cut	18.00 F	*18.00 FL
6	1		*BOX FILTER AIR OUTER FRONT	Cut	11.00 F	*11.00 FL
7	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	222.00 F	*200.00 FL
8	1		*COVER CLUTCH OUTER	Cut	28.00 F	*28.00 FL
9	1		*COVER CLUTCH OUTER DAMPER 1	Necessary	12.00 F	*12.00 FL
10	1		*COVER CLUTCH OUTER DAMPER 2	Necessary	7.00 F	*7.00 FL
11	1		*COVER CLUTCH OUTER DAMPER 3	Necessary	7.00 F	*7.00 FL
12	1		*COVER CLUTCH OUTER DAMPER 4	Necessary	12.00 F	*12.00 FL
13	1		*COVER SIDE CENTRE LH (WHITE)	Cut	30.00 F	*30.00 FL
14	1		*COVER SIDE CENTRE RH (WHITE)	Cut	30.00 F	*30.00 FL
15	1		*COVER UPPER HANDLE	Cracked	17.00 F	*17.00 FL
16	1		*EMBLEM	Necessary	10.00 F	*10.00 FL
17	2		*EMBLEM (YAMAHA) LOGO	Necessary	22.00 F	*22.00 FL
18	1		*FOOTREST REAR ASSY 1 LH	Not Necessary	33.00 F	*-FL
19	1		*FOOTREST REAR ASSY 1 RH	Not Necessary	33.00 F	*- FL
20	1		*LAMP SIGNAL FRONT RH	Scratched	35.00 F	*35.00 FL
21	1		*LEVER BRAKE LH	Scratched	18.00 F	*18.00 FL
22	1		*LEVER BRAKE RH	Serviceable	18.00 F	*-FL
23	1		*MIRROR LH	Cut	37.00 F	*37.00 FL
24	1		*MIRROR RH (CUT)	Not Consistent With The Impact	37.00 F	*- FL
25	1		*MUDGUARD FRONT (WHITE)	Cut	52.00 F	*52.00 FL
26	1		*PROTECTOR EXHAUST	Scratched	38.00 F	*38.00 FL
27	10		*RIVET	Necessary	20.00 F	*20.00 FL
28	2		*RIVET	Necessary	4.00 F	*4.00 FL
29	1		*SIDE STAND	Repair	24.00 F	*- FL
30	1		*STAND MAIN	Repair	66.00 F	*-FL
31	2		*STICKER (CERTIS CISCO) LOGO NEW MODEL LH / RH	Necessary	44.00 FS	*44.00 FS
32	1		*STICKER (CISCO) COVER CENTRE LH	Necessary	37.00 FS	*37.00 FS
33	1		*STICKER (CISCO) COVER CENTRE RH	Necessary	37.00 FS	*37.00 FS
34	1		*STICKER (CISCO) COWLING FRONT LH	Necessary	37.00 FS	*37.00 FS
35	1		*STICKER (CISCO) COWLING FRONT RH	Necessary	37.00 FS	*37.00 FS
36	1		*STICKER (CISCO) LINING COVER REAR LH	Necessary	15.00 FS	*15.00 FS
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	37.00 FS	*37.00 FS
F=Fra	nchise	part. S=	SpcNett. L=ListItemDisc.			
				Sub Total (S\$)	1,256.00	990.00
			- List Item Discou	nt on L Items 0.00/10.00% (S\$)	0.00	74.60
				Total Parts (S\$)	1,256.00	915.40
			Report was unsubmitted d	uring this print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR - LABOUR QUOTED FOR DISMANTLING INSTALLATION OF PARTS	AND New	1,008.00	300.00
2	SPRAY LACQUER ON CENTER COVER LH	New	91.00	60.00
3	SPRAY LACQUER ON CENTER COVER RH	New	91.00	60.00
4	SPRAY LACQUER ON FRONT COWLING LH	New	91.00	60.00
5	SPRAY LACQUER ON FRONT COWLING RH	New	91.00	60.00
6	SPRAY LACQUER ON FRONT MUDGUARD	New	49.00	30.00
7	SPRAY LACQUER ON FRONT PROTECTOR LH	New	63.00	50.00
8	SPRAY LACQUER ON FRONT PROTECTOR RH	New	63.00	50.00
9	SPRAY LACQUER ON TAIL COVER LEFT	New	63.00	50.00
10	SPRAY PAINT ON CENTER COVER LH	New	91.00	0.00
11	SPRAY PAINT ON CENTER COVER RH	New	91.00	0.00
12	SPRAY PAINT ON FRONT COWLING LH	New	91.00	0.00
13	SPRAY PAINT ON FRONT COWLING RH	New	91.00	0.00
14	SPRAY PAINT ON FRONT PROTECTOR LH	New	63.00	0.00
15	SPRAY PAINT ON FRONT PROTECTOR RH	New	63.00	0.00
16	SPRAY PAINT ON TAIL COVER LEFT	New	63.00	0.00
17	TRANSPORT CHARGES	New	56.00	35.00
		Gross Labour Cost (S\$)	2,219.00	755.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >