

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20008782/KVF3E2  
**Date:** 21/09/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.	Policy No:	
<b>Claimant Vehicle No :</b> GZ9797E	<b>Insured Vehicle No :</b>	EA292J
Date of Loss: 18/08/2020	Nature of Claim:	TP Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GZ9797E</b>		
Make & Model:	OPEL COMBO L2H1, 1.6 D CDTI (A)	Engine No:	263A50007701905
Reg. Date:	30/11/2016 (Man. Year: 2016)	Chassis No:	W0L6WYL11H9597446
Colour:	Red	Odometer:	42865 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Pirelli 3 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Pirelli 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,880.20	4,799.20	2,081.00	30.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	2,040.00	600.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,520.20</b>	<b>6,839.20</b>	<b>2,681.00</b>	<b>28.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,450.00</b>		
<b>(S\$)</b>	9,520.20	5,450.00	4,070.20	42.75
<b>+ GST 7.00/7.00% (S\$)</b>	666.41	381.50	284.91	42.75
<b>Nett Amount (S\$)</b>	<b>10,186.61</b>	<b>5,831.50</b>	<b>4,355.11</b>	<b>42.75</b>

### INSPECTION

Date of Assignment:	21/08/2020	
Date Inspected:	24/08/2020 Inspected At:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	7.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Sep 2020)	
<b>Parts:</b>	N/A	OPEL COMBO L2H1 1.6 D CDTI (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GZ9797E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Cracked	800.00 FL	*800.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	400.00 FL	*400.00 FL
3	1		*N/S REAR BUMPER RETAINER	Distorted	80.00 FL	*80.00 FL
4	1		*N/S REAR BUMPER REFLECTOR	Serviceable	70.00 FL	*- FL
5	1		*REAR END PANEL	Repair	500.00 FL	*- FL
6	1		*N/S TAIL GATE	Bent	1,900.00 FL	*1,720.00 FL
7	1		*N/S TAIL GATE HINGES	Lower Bent	500.00 FL	*250.00 FL
8	1		*TAIL GATE RUBBER	Serviceable	390.00 FL	*- FL
9	1		*TAIL GATE COMBO EMBLEM	Necessary	38.00 FL	*38.00 FL
10	1		*N/S TAIL LAMP	Cut	350.00 FL	*350.00 FL
11	1		*N/S REAR FENDER	Buckled	2,000.00 FL	*1,650.00 FL
12	1		*N/S REAR FENDER UNDER-SHIELD	Serviceable	350.00 FL	*- FL
13	1		*SET REAR BUMPER SENSOR	Serviceable	200.00 FS	*- FS
14	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,618.00</b>	<b>5,328.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	737.80	528.80
<b>Total Parts (\$\$)</b>	<b>6,880.20</b>	<b>4,799.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PUTTY & SPRAY PAINT	New	1,000.00	800.00
2	TO TRANSFER TAIL GATE FITTING	New	80.00	60.00
3	TO REMOVE & REFIG REAR N/S WINDSCREEN GLASS	New	100.00	100.00
4	TO REMOVE & REFIX FUEL TANK	New	80.00	60.00
5	TO ANTI-RUST	New	120.00	60.00
6	LABOUR CHARGES	New	1,200.00	900.00
7	TO REMOVE & REFIX REAR TRIMING	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,640.00</b>	<b>2,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >