

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008783/R1TF3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00029502000	
Claimant Vehicle No : GBJ2561H	Insured Vehicle No : GBJ3596B	
Date of Loss: 19/08/2020	Nature of Claim: TP	Claim No: SNM20D202958/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2561H		
Make & Model:	TOYOTA REGIUS ACE, 2.8 SUPER GL DARK PRIME II (A)	Engine No:	1GD8365260
Reg. Date:	04/03/2019 (Man. Year: 2018)	Chassis No:	GDH2011017301
Colour:	Grey	Odometer:	67133 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,731.33	1,136.88	594.45	34.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	800.00	390.00	32.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,921.33	1,936.88	984.45	33.70
+ GST 7.00/7.00% (\$\$)	204.49	135.58	68.91	33.70
Nett Amount (\$\$)	3,125.82	2,072.46	1,053.36	33.70

INSPECTION

Date of Assignment:	29/09/2020	
Date Inspected:	24/09/2020 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Feb 2021)	
Parts:	N/A	TOYOTA REGIUS ACE 2.8 SUPER GL DARK PRIME II (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2561H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR SIDE MIRROR (LH)	Cracked	1,128.75 FL	*1,128.75 FL
2	1		*FRT CORNER PANEL MIRROR BRACKET LH	Scratched	172.45 FL	*172.45 FL
3	1		*FRT BUMPER	Repair	541.25 FL	*- FL
4	1		*FRT BUMPER BRACKET (LH)	Serviceable	231.35 FL	*- FL
5	1		*FRONT DOOR MOULDING	Cut	150.98 FS	*150.98 FS
6	1		*FRT DOOR STICKER (LH)	Necessary	25.00 FS	*10.00 FS
					Sub Total (S\$)	2,249.78
					- List Item Discount on L Items 25.00/25.00% (S\$)	518.45
					Total Parts (S\$)	1,731.33

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK FRT LEFT DOOR,REPLACE ABOVE PARTS	New	350.00	250.00
2	TO REMOVE & REFIX DOOR GLASS	New	60.00	0.00
3	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	780.00	550.00
Gross Labour Cost (\$\$)			1,190.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >