



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1832Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40V3 BUMPER W LIP & FOG	DEFORMED	1,052.20	1,052.20
1	I40VC BRKT ASSY -FR BPR UP	NOT NECESSARY	22.40	-
1	I40VC BRACKET - FR BUMPER S	NOT NECESSARY	24.60	-
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40V2 COVER - FR BUMPER RH	CUT	93.60	93.60
1	HEADLAMP ASSY RH	CRACKED	1,388.00	1,388.00
	LESS 20% DISCOUNT		-520.56	-511.16
			2,082.24	2,044.64
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADVERTISEMENT LOGO RH (SN)	CUT	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING (REPAIR FRT FENDER RH).		400.00	280.00
	SPRAY PAINT ON AFFECTED AREA.		450.00	400.00
	TUFF COAT ON AFFECTED PARTS.		530.00	30.00
	WIRING CHARGE.		50.00	30.00
			1,430.00	740.00
GRAND TOTAL			3,612.24	2,884.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,300.00

Report Ref No. NS/INC20008784/T1qf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.