

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 6607J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SADDLEBAG LH	CUT	1,848.00	1,848.00
1	SADDLEBAG BRACKET LH	SERVICEABLE	374.40	-
1	MUFFLER ASSY LH	SERVICEABLE	2,287.20	-
1	FRONT FOOTREST LH	CUT	162.50	162.50
1	SET ENGINE GUARD COVER LH	CUT	300.00	300.00
	LESS 10% DISCOUNT		-497.21	-231.05
			4,474.89	2,079.45
	<u>SPECIAL NETT ITEMS</u>			
1	SADDLE BAG EMBLEM (SN)	NECESSARY	80.00	80.00
			80.00	80.00
	<u>LABOUR</u>			
	ALIGN BODY AND SUB FRAME.	NOT NECESSARY	350.00	-
	WORKMANSHIP TO REPAIR, RENEW DAMAGED AREAS.		450.00	200.00
			800.00	200.00
	GRAND TOTAL		5,354.89	2,359.45
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS3/III19020295/Dtf3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.