

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008799/ATF3Q2

Date: 22/03/2021

REFERENCE

| | | | | | |
|-------------------|------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | QIU WEI | Policy No: | 1900142676 | | |
| Date of Loss: | 16/05/2020 | Nature of Claim: | OD | Claim No: | 2248189180SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | | | |
|-----------------------------|-----------------------------------|--|--|-------------|-------------------|
| Reg No: | SMN7120M | | | Engine No: | CHZC31794 |
| Make & Model: | AUDI A3 SPORTBACK, 1.4 TFSI (A) | | | Chassis No: | WAUZZZ8V1KA107862 |
| Reg. Date: | 26/08/2019 (Man. Year: 2019) | | | Odometer: | 7470 km |
| Colour: | White | | | | |
| Engine Capacity: | 999 cc | | | | |
| Market Value/New Car Price: | S\$95,000.00 | | | | |
| Sum Insured (S\$): | Market Value/New Car Price | | | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 205/55R16 | Rear Tyre Size: | 205/55R16 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 3,532.00 | 2,541.36 | 990.64 | 28.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,872.00 | 2,672.00 | 2,200.00 | 45.16 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,404.00 | 5,213.36 | 3,190.64 | 37.97 |
| - Excess (S\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (S\$) | 7,804.00 | 4,613.36 | 3,190.64 | 40.88 |
| + GST 7.00/7.00% (S\$) | 546.28 | 322.94 | 223.34 | 40.88 |
| Nett Amount (S\$) | 8,350.28 | 4,936.30 | 3,413.98 | 40.88 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 21/08/2020 | | |
| Date Inspected: | 21/08/2020 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 4.0 days | | |

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------|-----|----------|-----------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT DOOR - LH | Dented | 2,267.00 FS | *1,813.60 FS |
| 2 | 1 | | *FRONT DOOR OUTER SEAL - LH | Necessary | 159.00 FS | *126.80 FS |
| 3 | 1 | | *BONDING AGENT | Not Necessary | 47.00 FS | *- FS |
| 4 | 1 | | *CLEANING SOLUTION | Not Necessary | 65.00 FS | *- FS |
| 5 | 1 | | *FRONT DOOR CATCH | Damaged | 104.00 FS | *83.20 FS |
| 6 | 1 | | *EXTERIOR DOOR HANDLE - LH | Cut | 359.00 FS | *286.80 FS |
| 7 | 1 | | *DOOR HANDLE CAP | Not Necessary | 51.00 FS | *- FS |
| 8 | 1 | | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |
| 9 | 1 | | *SUNDRIES | Necessary | 300.00 FS | *50.96 FS |
| Total Parts (\$\$) | | | | | 3,532.00 | 2,541.36 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED | New | 1,400.00 | 1,000.00 |
| 2 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 3 | TO REMOVE AND TRANSFER LHS FRONT DOOR;S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES | New | 280.00 | 280.00 |
| 4 | TO RESPRAY LHS FRONT DOOR, LHS SILL PANEL ,DOOR HANDLE AND RHS REAR FENDER | New | 3,000.00 | 1,200.00 |
| Gross Labour Cost (S\$) | | | 4,872.00 | 2,672.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >