

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008800/KES3Q2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100088019
Claimant Vehicle No :	SGX9293C	Insured Vehicle No :	SJG2213J
Date of Loss:	13/07/2020	Nature of Claim:	TP
		Claim No:	5599478401SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX9293C		
Make & Model:	MERCEDES-BENZ C180, 1.6 AVANT GARDE (A)	Engine No:	27491030957064
Reg. Date:	26/05/2017 (Man. Year: 2017)	Chassis No:	WDD2050402R276991
Colour:	Metallic Grey	Odometer:	30671 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,181.40	2,925.90	1,255.50	30.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	550.00	400.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,131.40	3,475.90	1,655.50	32.26
+ GST 7.00/7.00% (S\$)	359.20	243.31	115.89	32.26
Nett Amount (S\$)	5,490.60	3,719.21	1,771.39	32.26
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,081.21		

INSPECTION

Date of Assignment:	21/08/2020		
Date Inspected:	24/08/2020	Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Bent	1,831.00 FL	*1,831.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	751.00 FL	*- FL
3	1		*REAR REINFORCEMENT INNER PARTS	Cracked	155.00 FL	*155.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Dented	295.00 FL	*295.00 FL
5	4		*LOWER GARNISH PARKING SENSOR	Shorted (2 PCS ONLY)	1,288.00 FL	*644.00 FL
6	1		*REAR LOWER GARNISH CHROME	Cracked	326.00 FL	*326.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,646.00	3,251.00
- List Item Discount on L Items 10.00/10.00% (S\$)	464.60	325.10
Total Parts (S\$)	4,181.40	2,925.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	500.00	300.00
2	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING & ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	450.00	250.00
Gross Labour Cost (S\$)			950.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >