

ASS. REC. BY:

REF:

14/20008800/Ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGX 9293C Yr Regn: 05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer C180

c.c

1595

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

30071

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2050402R 27691

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

13/7/20

D.O.I.

24/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/8 @ 3475.90 Car Insured

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJG2213J
Accident Date : 13-Jul-2020

No. : 06193

Date : 15-Jul-2020

Our Ref : 020073 (AIG) / CHAN

PAGE : 1

TANG YAN HIM
993 BUKIT TIMAH ROAD
#05-14
Singapore 589631

*Not Authorised
Resurvey Before
3 days*

ESTIMATED COST OF REPAIR FOR M/BENZ C180 AVANTAGRDE SGX9293C

1 pc	Rear bumper fascia	R	1,831.00	✓
1 pc	Rear bumper reinforcement	R	751.00	X
1 pc	Rear reinforcement inner parts	CM	155.00	✓
1 pc	Rear bumper lower garnish	R	295.00	✓
2 pcs	Lower garnish parking sensor		1,288.00	✓
1 pc	rear lower garnish chrome	CM	326.00	✓
			4,646.00	
		Less 10% :	464.60	
			4,181.40	
To putty and spray replaced parts			500.00	300
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts			450.00	250
Total :			S\$ 5,131.40	

Singapore Dollars Five Thousand One Hundred and
Thirty One and Cents Forty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire Vehicle Registration Details

Vehicle Registration Details

Vehicle No.

SGX9293C

Make/ Model

MERCEDES BENZ/C180 AVANTGARDE (R17 LED)

Vehicle Scheme

-

Current Propellant

Petrol

Chassis No.

WDD2050402R276991

Vehicle Type

Passenger Motor Car

Owner's Details

Owner Name:

TANG YAN HIM

Owner ID Type:

Singapore NRIC

NRIC/Passport/Company Cert No.:

S0573208E

Registered Address:

993 BUKIT TIMAH ROAD #05-14 SINGAPORE 589631