



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2105367

INV Date 01/08/2021

Reference CC4/LPC20008817/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLT 6619D
Insured Veh. YN 477M
Claim No. 19/20/20/VC00/023559
Policy No. Z/19/VC00/104602
Accident Date 20/08/2020
Inspection Date 21/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20008817/Kpa3q2 Date: 01/08/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 477M	Veh. Inspected	SLT 6619D	
Policy No.	Z/19/VC00/104602	Coverage (\$)	0.00	
Claim No.	19/20/20/VC00/023559	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	21/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI TUCSON (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHJ3812VJU606234	Colour	METALLIC GREY	
Odometer	54300 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R19	CONTINENTAL	9 mm	
L/H Front Tyre	235/50 R19	CONTINENTAL	9 mm	
R/H Rear Tyre	235/50 R19	CONTINENTAL	9 mm	
L/H Rear Tyre	235/50 R19	CONTINENTAL	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2020	Inspection Date	21/08/2020	
Survey held at	AT AUTO CONSULTANT 113 TECK WHYE LANE #05-650 SINGAPORE 680113			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 6619D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	BENT	1,658.30	1,628.00
1	TAIL GATE LOWER NUMBER PLATE GARNISH	CRACKED	285.20	285.20
1	TAIL GATE REFLECTOR	BROKEN	871.90	681.60
1	TAIL GATE EMBLEM "HYUNDAI"	NECESSARY	59.70	59.70
1	TAIL GATE EMBLEM "TUCSON"	NECESSARY	59.70	59.70
1	TAIL GATE EMBLEM "TURBO"	NECESSARY	59.70	59.70
1	TAIL GATE INNER TRIM	SERVICEABLE	256.20	-
1	TAIL GATE LOCK	TO REPAIR SEE LABOUR	198.20	-
1	TAIL GATE WEATHERSTRIP	SERVICEABLE	234.10	-
1	REAR BUMPER	BENT	935.60	798.00
1	REAR BUMPER LOWER LID	DENTED	365.70	365.70
1	REAR BUMPER REFLECTOR	CRACKED	120.90	120.90
1	REAR REINFORCEMENT	CRACKED	289.10	289.10
1	REAR END PANEL	TO REPAIR SEE LABOUR	665.10	-
1	TAIL LAMP LH	BROKEN	895.30	895.30
1	TAIL LAMP POCKET PANEL	BENT	333.90	333.90
1	REAR FENDER LH	BUCKLED	2,042.70	2,042.70
1	REAR FENDER INNER TRIM	SERVICEABLE	836.40	-
1	REAR FENDER WHEEL ARCH GARNISH	SERVICEABLE	190.00	-
1	REAR WHEEL INNER GARNISH	SERVICEABLE	185.30	-
1	TAIL GATE WINDSCREEN (ADDITIONAL)	CUT	660.30	660.30
	LESS 20% DISCOUNT		-2,240.66	-1,655.96
			8,962.64	6,623.84
	<u>SPECIAL NETT ITEMS</u>			
1	SET TAIL GATE WIND SCREEN SEALANT (SN)	NECESSARY	180.00	40.00
1	SET REAR FENDER QUARTER GLASS MOULDING (SN)	NECESSARY	158.00	158.00
1	SET BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET NUMBER PLATE & GARNISH (SN)	SERVICEABLE	60.00	-

Report Ref No. CC4/LPC20008817/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REVERSE SENSOR ORIGINAL @\$135.00 (SN)	SHORTED (1 PC ONLY)	270.00	135.00
1	BUMPER TOP ANTI SCRATCHES AUTO HEALING STICKER (SN)	NECESSARY	250.00	120.00
1	SET TAIL GATE WIND SCREEN SEALANT (ADDITIONAL) (SN)	NECESSARY	180.00	40.00
			1,148.00	543.00
	LABOUR			
	CERAMIC COATING FOR AFFECTED AREA.	NOT NECESSARY	500.00	-
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAIL GATE LOCK AND REAR END PANEL.		1,200.00	700.00
	SPRAY PAINTING ON ACCIDENT AREAS.		1,500.00	1,000.00
	WIRING CHARGES.		100.00	20.00
	R/R TAIL GATE WIND SCREEN.		180.00	120.00
	R/R REAR FENDER QUARTER GLASS LH.		180.00	60.00
	R/R PETROL PIPE TO FACILITATE HOT WORK.	NOT NECESSARY	200.00	-
	R/R REAR BOOT COMPARTMENT/REAR SEAT TO FACILITATE REPAIR.		300.00	60.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS.		150.00	60.00
	R/R TAIL GATE WIND SCREEN (ADDITIONAL).		180.00	120.00
			4,490.00	2,140.00
GRAND TOTAL			14,600.64	9,306.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,350.00

Report Ref No. CC4/LPC20008817/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 6619D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 6619D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 6619D

RE-INSPECTION

