

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

NOT Authorized
11 Aug 87
Resurvey After Painting
7 days

Date of Estimate: 20.08.2020
Vehicle No: SLT6619D
Owner: LOON XI YANG
Date of Accident: 20.08.2020
Make & Model: HYUNDAI TUCSON 1.6 GLS
Chassis No : KMHJ3812VJU606234

ESTIMATE FOR ACCIDENT VEHICLE NOS SLT6619D

PARTS

- | | | |
|----|---|--------------------------------------|
| 1 | 1 | Tail gate |
| 2 | 1 | Tail gate lower number plate garnish |
| 3 | 1 | Tail gate reflector |
| 4 | 1 | Tail gate emblem "HYUNDAI" |
| 5 | 1 | Tail gate emblem "TUCSON" |
| 6 | 1 | Tail gate emblem "TURBO" |
| 7 | 1 | Tail gate inner trim |
| 8 | 1 | Tail gate lock |
| 9 | 1 | Tail gate weather strip |
| 10 | 1 | Rear bumper |
| 11 | 1 | Rear bumper lower lid |
| 12 | 1 | Rear bumper reflector |
| 13 | 1 | Rear reinforcement |
| 14 | 1 | Rear end panel |
| 15 | 1 | Tail lamp LH |
| 16 | 1 | Tail lamp pocket panel |
| 17 | 1 | Rear fender LH |
| 18 | 1 | Rear fender inner trim |
| 19 | 1 | Rear fender wheel arch garnish |
| 20 | 1 | Rear wheel inner garnish |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUB TOTAL
LESS 20 %
DISCOUNTED SUB TOTAL

Ag	\$1,658.30	✓
CM	\$285.20	✓
BR	\$871.90	✓
NA	\$59.70	✓
NA	\$59.70	✓
NA	\$59.70	✓
SN	\$256.20	X
R	\$198.20	X
SN	\$234.10	X
BR	\$935.60	✓
NA	\$365.70	✓
CM	\$120.90	✓
	\$289.10	?
	\$665.10	?
BR	\$895.30	✓
	\$333.90	?
BR	\$2,042.70	✓
SN	\$836.40	X
SN	\$190.00	X
SN	\$185.30	X
\$10,543.00		
\$2,108.60		
\$8,434.40		

S. NETT ITEM

- | | | |
|---|------|--|
| 1 | 1set | Tail gate wind screen sealant |
| 2 | 1set | Rear fender quarter glass moulding |
| 3 | 1set | Bumper clips |
| 4 | 1set | Number plate & garnish |
| 5 | 2 | Reverse sensor original X 2 |
| 6 | 1 | Bumper top anti scratches auto healing sticker |
| 7 | 1 | Ceramic coating for affected area |

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

@ \$135.00

NA	\$180.00	4050
NA	\$158.00	✓
NA	\$50.00	✓
SN	\$60.00	X
Shay	\$270.00	4
NA	\$250.00	12050
	\$500.00	?
\$1,468.00		
\$0.00		
\$1,468.00		

LABOUR

- | | |
|---|--|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | R/R tail gate wind screen |
| 5 | R/R rear fender quarter glass LH |
| 6 | R/R petrol pipe to facilitate hot work |
| 7 | R/R rear boot compartment/rear seat to facilitate repair |
| 8 | Apply undercoating to above affected areas |

SUB TOTAL (LABOUR)

\$1200	1200.00	601
	1,500.00	1000
	100.00	201
	180.00	1201
NA	180.00	601
	200.00	X
	300.00	601
	150.00	601
\$2,730.00		