

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

NOT Authorized
11 Rm @ 7350k
Purvey After Paint
Folan

Date of Estimate: 20.08.2020
Vehicle No: SLT6619D
Owner: LOON XI YANG
Date of Accident: 20.08.2020
Make & Model: HYUNDAI TUCSON 1.6 GLS
Chassis No : KMHJ3812VJU606234

ESTIMATE FOR ACCIDENT VEHICLE NOS SLT6619D

PARTS

1	1 Tail gate → 1628
2	1 Tail gate lower number plate garnish
3	1 Tail gate reflector → 681.60
4	1 Tail gate emblem "HYUNDAI"
5	1 Tail gate emblem "TUCSON"
6	1 Tail gate emblem "TURBO"
7	1 Tail gate inner trim
8	1 Tail gate lock
9	1 Tail gate weather strip
10	1 Rear bumper 798
11	1 Rear bumper lower lid
12	1 Rear bumper reflector
13	1 Rear reinforcement
14	1 Rear end panel
15	1 Tail lamp LH
16	1 Tail lamp pocket panel
17	1 Rear fender LH →
18	1 Rear fender inner trim
19	1 Rear fender wheel arch garnish
20	1 Rear wheel inner garnish

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ry	\$1,658.30	✓
CM	\$285.20	✓
Bu	\$871.90	✓
Re	\$59.70	✓
Re	\$59.70	✓
Re	\$59.70	✓
Re	\$256.20	X
Re	\$198.20	X
Re	\$234.10	X
Re	\$935.60	✓
Re	\$365.70	✓
CM	\$120.90	✓
CM	\$289.10	✓
Re	\$665.10	X
Bu	\$895.30	✓
Re	\$333.90	✓
Bu	\$2,042.70	✓
Re	\$836.40	X
Re	\$190.00	X
Re	\$185.30	X
	\$10,543.00	
	\$2,108.60	
	\$8,434.40	

SUB TOTAL
LESS 20 %
DISCOUNTED SUB TOTAL

S. NETT ITEM

1	1set Tail gate wind screen sealant
2	1set Rear fender quarter glass moulding
3	1set Bumper clips
4	1set Number plate & garnish
5	2 Reverse sensor original X 2
6	1 Bumper top anti scratches auto healing sticker
7	1 Ceramic coating for affected area

@ \$135.00

Re	\$180.00	✓
Re	\$158.00	✓
Re	\$50.00	✓
Re	\$60.00	X
Re	\$270.00	✓
Re	\$250.00	✓
Re	\$500.00	✓
	\$1,468.00	
	\$0.00	
	\$1,468.00	

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges
4	R/R tail gate wind screen
5	R/R rear fender quarter glass LH
6	R/R petrol pipe to facilitate hot work
7	R/R rear boot compartment/rear seat to facilitate repair
8	Apply undercoating to above affected areas

\$1200	1200.00	601
	1,500.00	1000
	100.00	201
	180.00	1201
na	180.00	601
	200.00	X
	300.00	601
	150.00	601
	\$2,730.00	

SUB TOTAL (LABOUR)

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 20.08.2020
Vehicle No: SLT6619D
Owner: LOON XI YANG
Date of Accident: 20.08.2020
Make & Model: HYUNDAI TUCSON 1.6 GLS
Chassis No : KMHJ3812VJU606234

SUPPLEMENTARY ESTIMATE FOR ACCIDENT VEHICLE NOS SLT6619D

PARTS

1 1 Tail gate windscreen ✓

SUB TOTAL
LESS 20 %
DISCOUNTED SUB TOTAL

cut \$660.30
\$660.30
\$132.06
\$528.24

S. NETT ITEM

1 1set Tail gate wind screen sealant ✓

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

nec \$180.00 \$40 SN
\$180.00
\$0.00
\$180.00

LABOUR

1 R/R tail gate wind screen ✓

SUB TOTAL (LABOUR)

180.00 120.00
\$180.00

SUB TOTAL (S.NETT)

\$180.00

SUB TOTAL (PARTS)

\$528.24

SUB TOTAL (LABOUR)

\$180.00

ESTIMATED GRAND TOTAL

\$888.24

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP
