



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 688J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (CONSISTENT)	TORN	860.00	594.00
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	62.40	-
1	FRONT FENDER (CONSISTENT)	DENTED	630.20	630.20
1	FRONT FENDER INNER COWLING (CONSISTENT)	NOT NECESSARY	140.00	-
	LESS 20% DISCOUNT		-338.52	-244.84
			1,354.08	979.36
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET FRONT FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
			40.00	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING,REMOVAL AND REPLACING PARTS.		800.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		800.00	400.00
	TUFF COAT.	NOT NECESSARY	200.00	-
	WIRING CHECK.	NOT NECESSARY	50.00	-
			1,850.00	700.00
	<b>GRAND TOTAL</b>		<b>3,244.08</b>	<b>1,679.36</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,679.36</b>

Report Ref No. CC4/ASM20008823/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.