

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008850/ETF3E2

Date: 03/09/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00005742000

Claimant Vehicle
No : YM1080YInsured Vehicle
No : YP3549J

Date of Loss: 20/08/2020

Nature of Claim: TP

Claim
No: SNM20D202975

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YM1080Y

Make & Model: MITSUBISHI FE639ET0SRDE, 3.9 D (M)

Engine No: 4D34K41157

Reg. Date: 29/08/2005 (Man. Year: 2005)

Chassis No: FE639EA47455

Colour: Red

Odometer: 438372 km

Engine Capacity: 3908 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00-16	Rear Tyre Size:	7.00-16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,415.22	1,323.22	92.00	6.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,060.00	740.00	41.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,215.22	2,383.22	832.00	25.88
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	3,215.22	1,900.00	1,315.22	40.91
+ GST 7.00/7.00% (S\$)	225.07	133.00	92.07	40.91
Nett Amount (S\$)	3,440.29	2,033.00	1,407.29	40.91

INSPECTION

Date of Assignment: 26/08/2020

Date Inspected: 25/08/2020 Inspected At:

 Ryder Auto Workshop LLP (HQ)
 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Sep 2020)	
Parts:	N/A	MITSUBISHI FE639ET0SRDE 3.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM1080Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	536.00 FL	*536.00 FL
2	1		*FRONT O/S CORNER PANEL	Dented	213.50 FL	*213.50 FL
3	1		*FRONT O/S SIGNAL LAMP	Cut	175.60 FL	*175.60 FL
4	1		*FRONT O/S FOG LAMP	Broken	150.60 FL	*150.60 FL
5	1		*FRONT O/S HEAD LAMP	Broken	568.60 FL	*568.60 FL
6	4		*FRONT O/S CORNER PANEL CLIPS	Necessary	32.00 FS	*10.00 FS
7	1		*FRONT ADVERTISEMENT	Necessary	150.00 FS	*80.00 FS
					Sub Total (\$\$)	1,826.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	411.08
					Total Parts (\$\$)	1,415.22

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE,STRAIGHTEN & WELDING	New	900.00	600.00
2	TO SPRAY PAINTING	New	800.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO RE-SEAL ANTI RUST	New	50.00	30.00
Gross Labour Cost (S\$)			1,800.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >