

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : YM1080Y

Model: MIT FUSO

Accident Date : 20/8/2020

(29/8/2005)-(28/8/2025)

Location : SUNGEI KADUT STREET 1

3P: YP3549J (China taiping)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front panel / <i>DD</i>	536.00	-	-
2	1 pc	Front o/s corner pannel / <i>DD</i>	213.50	-	-
3	4pcs	Front o/s corner pannel clips / <i>APC</i>	-	32.00	-
4	1 pc	Front o/s signal lamp / <i>CUT</i>	175.60	-	-
5	1 pc	Front advertisement / <i>APC</i>	-	150.00	80
Sub-Total:			925.10	182.00	0.00
			25%	0%	0%
After Less %:			693.83	182.00	0.00
Labour					
1		To dismantle, straighten & welding.	900.00	600	
2		To spray painting.	800.00	400	
3		To check wiring.	50.00	30	
4		To re-seal anti-rust.	50.00	30	
Sub-Total:			1,800.00		
Total:			2,675.83		
After Less 20%:			2,140.66		

(list)
(list)
10 / (nett)
(list)
(nett)

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



Steve (LKK)

WHL PUL

25/8/20, 11.00am

L/S, Ry AL SH

bizSAFE 8778 1999
24 hr accident call

5 days

list - 925.10

- 75%

693.83

Nett - 90

Labour - 1060

= 1843.82



PAYNOW

Mobil 1

SUP - 539.40

= 2383.22

L/S - 1906.57

= 1900

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: