

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008851/QSF3E2
Date: 11/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30868219000
Claimant Vehicle No :	SLJ573T	Insured Vehicle No :	YP8133S
Date of Loss:	20/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202972/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ573T	Engine No:	LEB4262715
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71043105
Reg. Date:	28/11/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,621.28	24,534.28	3,087.00	11.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,030.00	4,780.00	3,250.00	40.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,651.28	29,314.28	6,337.00	17.77
+ GST 7.00/7.00% (S\$)	2,495.59	2,052.00	443.59	17.77
Nett Amount (S\$)	38,146.87	31,366.28	6,780.59	17.77

INSPECTION

Date of Assignment:	21/08/2020		
Date Inspected:	24/08/2020	Inspected At:	Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-35/36 Carros Centre Singapore 737569
Estimated Period of Repair:	15.0 days		

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$2,008.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2021)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ573T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	2,300.00 FL	*2,300.00 FL
2	1		*FRONT BONNET	Dented	1,380.00 FL	*1,380.00 FL
3	1		*FRONT BONNET LH HINGE	Bent	60.00 FL	*60.00 FL
4	1		*FRONT BONNET RH HINGE	Bent	60.00 FL	*60.00 FL
5	1		*FRONT BONNET INSULATOR	Necessary	165.00 FL	*165.00 FL
6	1		*FRONT BONNET LOCK ASSY	Jammed	195.00 FL	*195.00 FL
7	1		*FRONT BONNET LOCK CATCH	Serviceable	150.00 FL	*- FL
8	1		*FRONT BONNET SEAL	Crumpled	75.00 FL	*75.00 FL
9	1		*F/L FENDER	Dented	1,100.00 FL	*1,100.00 FL
10	1		*F/R FENDER	Dented	1,100.00 FL	*1,100.00 FL
11	1		*F/L FENDER INNER LINER	Serviceable	240.00 FL	*- FL
12	1		*F/R FENDER INNER LINER	Deformed	240.00 FL	*240.00 FL
13	1		*F/FENDER HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
14	1		*F/R FENDER HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
15	1		*FRONT SUPPORT PANEL TOP COVER	Crumpled	250.00 FL	*250.00 FL
16	1		*FRONT SUPPORT PANEL	Dented	1,050.00 FL	*1,050.00 FL
17	1		*RADIATOR GRILLE CENTER MOULDING	Crumpled	390.00 FL	*390.00 FL
18	1		*RADIATOR GRILLE BASE	Crumpled	325.00 FL	*325.00 FL
19	1		*RADIATOR GRILLE LOWER MOULDING	Crumpled	330.00 FL	*330.00 FL
20	1		*RADIATOR GRILLE EMBLEM	Necessary	48.00 FL	*48.00 FL
21	1		*F/L HEADLAMP	Crumpled	1,215.00 FL	*1,215.00 FL
22	1		*F/R HEADLAMP	Crumpled	1,215.00 FL	*1,215.00 FL
23	1		*F/L HEADLAMP LOWER BRACKET	* Check	115.00 FL	*- FL
24	1		*F/R HEADLAMP LOWER BRACKET	* Check	115.00 FL	*- FL
25	1		*FRONT BUMPER	Dented	1,350.00 FL	*1,350.00 FL
26	1		*FRONT BUMPER REINFORCEMENT	Bent	660.00 FL	*660.00 FL
27	1		*FRONT BUMPER RH TOW COVER	Necessary	54.00 FL	*54.00 FL
28	1		*FRONT BUMPER RH SIDE RETAINER	Broken	21.00 FL	*21.00 FL
29	1		*FRONT BUMPER LH SIDE RETAINER	Broken	21.00 FL	*21.00 FL
30	1		*FRONT BUMPER RH FOG LAMP COVER	Missing	150.00 FL	*150.00 FL
31	1		*FRONT BUMPER LH FOG LAMP COVER	Serviceable	150.00 FL	*- FL
32	1		*FRONT BUMPER LOWER GRILLE	Crumpled	294.00 FL	*294.00 FL
33	1		*FRONT WINDSCREEN WASHER TANK	Crumpled	250.00 FL	*250.00 FL
34	1		*FRONT RH WHEEL HOUSE UPPER MEMBER	Dented	480.00 FL	*480.00 FL
35	1		*FRONT RH WHEEL HOUSE LOWER EXTENSION	Bent	480.00 FL	*480.00 FL
36	1		*RADIATOR ASSY	Dented	1,800.00 FL	*1,800.00 FL
37	1		*AIR CON CONDENSER	Dented	900.00 FL	*900.00 FL
38	1		*RADIATOR FAN MOTOR	* Check	850.00 FL	*- FL
39	1		*AIRCON CONDENSER MOTOR	* Check	700.00 FL	*- FL
40	1		*RADIATOR SHROUD	* Check	250.00 FL	*- FL
41	1		*INLET MANIFOLD	* Check	480.00 FL	*- FL
42	1		*DRIVER AIR BAG	Broken	3,000.00 FL	*3,000.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*PASSENGER AIR BAG	Broken	3,000.00 FL	*3,000.00 FL
44	1		*DASHBOARD	Broken	2,000.00 FL	*2,000.00 FL
45	1		*SRS ECU	Necessary	2,030.00 FL	*2,030.00 FL
46	1		*F/R CRASH SENSOR	Necessary	200.00 FL	*200.00 FL
47	1		*F/L CRASH SENSOR	Necessary	200.00 FL	*200.00 FL
48	1		*F/L SAFETY BELT	Jammed	750.00 FL	*750.00 FL
49	1		*F/R SAFETY BELT	Jammed	750.00 FL	*750.00 FL
50	1		*F/L SAFETY BELT BUCKLE	Serviceable	120.00 FL	*- FL
51	1		*F//R SAFETY BELT BUCKLE	Serviceable	120.00 FL	*- FL
52	1		*STEERING REEL COIL	Necessary	400.00 FL	*400.00 FL
53	1		*SET WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
54	1		*SET BODY SEALANT	Necessary	300.00 FS	*60.00 FS
55	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
56	1		*SET FRONT NUMBER PLATE	Necessary	80.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	34,371.60	30,626.60
- List Item Discount on L Items 20.00/20.00% (\$)	6,750.32	6,092.32
Total Parts (\$)	27,621.28	24,534.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, F/R WHEEL HOUSING UPPER MEMBER AND F/R CHASSIS OUTER MEMBER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS. ALSO INCLDE CUTTING AND WELDING OF DAMAGED PARTS	New	2,500.00	1,900.00
2	TO RESPRAY FRONT BONNET, BOTH FRONT FENDERS, SUPPORT PANEL, F/R WHEELHOUSE AND FRONT BUMPER (INNER/OUTER)	New	1,800.00	1,400.00
3	TO REMOVE & INSTALL FRONT WINDSCREEN	New	160.00	120.00
4	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	60.00
5	TO LABOUR CHARGE FOR REMOCING AND INSTALLING ENGINE ASSY OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	500.00	350.00
6	TOWING FEE	New	50.00	50.00
7	TO LABOUR CHARGE FOR REMOVING AIR CON SYSTEM OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND INCUDE VACUUMING OF AIR CON GAS	New	300.00	100.00
8	TO LABOUR CHARGE FOR REMOVING AND INSATTING DASHBOARD TO FACILITATE REPLACEMENT OF SRS AIR BAG	New	500.00	250.00
9	TO CONFIGURE AND REPROGRAME SRS AIR BAG ECU BACK TO FACTORY SPECIFICATION	New	500.00	200.00
10	TO REMOVE AND INSTALL FRONT ENGINE ASSY OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	500.00	0.00
11	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS	New	160.00	0.00
12	TO ACTIVATE AND DEACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS }	New	300.00	350.00
13	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS }	New	300.00	0.00
14	TO LABOUR CHARGE FOR REMOVING AIR CON SYSTEM OUT TO FACILITATE REPLACEMENT OF DAMAGED AIR CON PARTS. ALSO INCLUDE VACUUMING AND RENEWING AIR CON GAS	New	380.00	0.00
Gross Labour Cost (\$\$)			8,030.00	4,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >