

Shirley Hiew (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Thursday, 3 September 2020 12:07 pm
To: Shirley Hiew (LKK Auto)
Subject: FW: SLJ 573T

From: Siak Tong Sim [mailto:siaktong@lioncityrentals.com.sg]
Sent: Monday, August 24, 2020 5:38 PM
To: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Subject: Re: SLJ 573T

Sun Pin
So confirm \$16K to repair

On Mon, 24 Aug 2020, 17:24 Oi Sun Pin (LKK Auto), <sunpin@lkkauto.com> wrote:

Hi Mr Sim,

Can, the limit repair 16K

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Siak Tong Sim [mailto:siaktong@lioncityrentals.com.sg]
Sent: Monday, August 24, 2020 5:20 PM
To: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Subject: Re: SLJ 573T

Sun Pin

Sorry typo error is 16k not 15k

On Mon, 24 Aug 2020, 17:13 Oi Sun Pin (LKK Auto), <sunpin@lkkauto.com> wrote:

Hi Mr Sim,

SLJ573T have repair limits.

the limit of the cost of repair is \$14,000

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

