

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008858/AVF3E2

Date: 07/12/2020

REFERENCE

Insured/Claimant:	WANG WEN	Policy No:	2070044058
Date of Loss:	21/08/2020	Nature of Claim:	OD
		Claim No:	7120462345SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8919T		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC32587
Reg. Date:	19/03/2020 (Man. Year: 2019)	Chassis No:	WAUZZZGA9KA082224
Colour:	Silver	Odometer:	3286 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,888.00	8,866.16	10,021.84	53.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,664.00	3,784.00	3,880.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,552.00	12,650.16	13,901.84	52.36
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	26,152.00	12,250.16	13,901.84	53.16
+ GST 7.00/7.00% (S\$)	1,830.64	857.51	973.13	53.16
Nett Amount (S\$)	27,982.64	13,107.67	14,874.97	53.16

INSPECTION

Date of Assignment:	24/08/2020	
Date Inspected:	24/08/2020	Inspected At: 24 BENOI SECTOR
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,854.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	195.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	167.00 FS	*- FS
5	1		*FRONT BUMPER END CAP - LH	Not Necessary	34.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	296.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	154.00 FS	*- FS
8	1		*WHEEL SPOILER - LH	Not Necessary	34.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	35.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cut	1,395.00 FS	*1,116.00 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	123.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	679.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	77.00 FS	*- FS
14	1		*FOAM FILLER PIECE COVER	Cut	99.00 FS	*79.04 FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	35.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
17	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
18	1		*FRONT FENDER - LH	Dented	1,134.00 FS	*907.20 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - LH	Not Necessary	16.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - LH	Not Necessary	47.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Not Necessary	16.00 FS	*- FS
23	1		*FRONT FENDER BRACE - LH	Not Necessary	37.00 FS	*- FS
24	1		*FRONT FENDER BRACKET	Not Necessary	23.00 FS	*- FS
25	1		*WHEEL HOUSING LINER - LH	Not Necessary	194.00 FS	*- FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
27	1		*BONNET	Dented	2,757.00 FS	*2,205.60 FS
28	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
29	1		*BONNET STRIKER - LH	Not Necessary	109.00 FS	*- FS
30	1		*BONNET IMPACT PROTECTION - CENTRE / LH / RH (3 pcs)	Necessary	90.00 FS	*70.48 FS
31	1		*BONNET LID LOCK	Not Necessary	212.00 FS	*- FS
32	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
33	1		*HEADLIGHT - LH	Cracked	4,859.00 FS	*3,887.20 FS
34	1		*LED WITH HEAT SINK - LH	Not Necessary	725.00 FS	*- FS
35	1		*MAIN LIGHT ELECTRONICS POWER MODULE - LH	Not Necessary	749.00 FS	*- FS
36	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	551.00 FS	*- FS
37	1		*HEADLAMP REPAIR KIT	Not Necessary	64.00 FS	*- FS
38	1		*HEADLIGHT - HOSE	Not Necessary	29.00 FS	*- FS
39	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
40	1		*LIFT SYLINER - LH	Not Necessary	141.00 FS	*- FS
41	1		*LIFT SYLINDER HOSE	Not Necessary	175.00 FS	*- FS
42	2		*FRONT WHEEL COVER - LH / RH	Necessary	636.00 FS	*508.80 FS
43	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
44	1		*SUNDRIES	Necessary	300.00 FS	*15.36 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 18,888.00 8,866.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULES	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	3,400.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			7,664.00	3,784.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >