

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2020		24 Aug 2020 14:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: TKB C-E CONTRACTOR PTE LTD , Co. Reg. No.: 198600003M									
Main Claimant: CKR CONTRACT SERVICES PTE LTD , Co. Reg. No.: 200416739G									
Vehicle Reg. No.: XD9382H		Date of Loss: 20/08/2020 07:00 - :59 [73 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D202976/C02/TKL		Policy/Cover Note No.: DMCVSNW00023732003 (Comprehensive) Coverage: 08/04/2020 - 07/04/2021							
Vehicle Reg. No. (Insured): YN7681T		Policy No. (Claimant): Excess: S\$550.00							
Repairer: R&s Engineering Works Pte Ltd (HQ) 13 PIONEER SECTOR 1, 628424 Pioneer - Tel: 62647001									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/09/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD9382H (SNM20D202976/C02/TKL)**
[YN7681T]

TP

CKR CONTRACT SERVICES PTE LTD

Aug 20 2020 7:00AM

[TKB C-E CONTRACTOR PTE LTD]

R&s Engineering Works Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/08/20 20:53	Odometer Reading	Load JPG	☒
2	25/08/20 20:53	Chassis Number	Load JPG	☒
3	25/08/20 20:53	General View	Load JPG	☒
4	25/08/20 20:53	General View	Load JPG	☒
5	25/08/20 20:53	General View	Load JPG	☒
6	25/08/20 20:53	General View	Load JPG	☒
7	25/08/20 20:53	General View	Load JPG	☒
8	25/08/20 20:53	General View	Load JPG	☒
9	25/08/20 20:53	General View	Load JPG	☒
10	25/08/20 20:53	General View	Load JPG	☒
11	25/08/20 20:53	General View	Load JPG	☒
12	25/08/20 20:53	General View	Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/08/20 14:01	Pre-Repair Survey	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI20008868/R1QF3S2**Date:** 27/08/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00023732003
Claimant Vehicle No :	XD9382H	Insured Vehicle No :	YN7681T
Date of Loss:	20/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202976/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD9382H	Engine No:	6806239
Make & Model:	SCANIA P400CB8X4MHZ, 12.7 D (M)	Chassis No:	YS2P8X40005345971
Reg. Date:	18/07/2014 (Man. Year: 2014)	Odometer:	264670 km
Colour:	White		
Engine Capacity:	12742 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8/8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	24/08/2020		
Date Inspected:	25/08/2020	Inspected At:	R&s Engineering Works Pte Ltd (HQ) 13 PIONEER SECTOR 1 Singapore 628424
Estimated Period of Repair:	1.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500.00 - \$1,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Aug 2020)	
Parts:	N/A	SCANIA P400CB8X4MHZ 12.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD9382H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >