

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008874/KES3Q2

Date: 18/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070013129

Claimant
Vehicle No : SMA7463S **Insured Vehicle No :** SJH4429K

Date of Loss: 22/08/2020 Nature of Claim: TP Claim No: 0743147078SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA7463S		
Make & Model:	HYUNDAI I30, 1.4 GLS 5DR DCT TURBO (A)	Engine No:	G4LDJD012646
Reg. Date:	19/06/2018 (Man. Year: 2018)	Chassis No:	TMAH3513VJJ065190
Colour:	Metallic Gold	Odometer:	47717 km
Engine Capacity:	1353 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,972.85	6,344.64	4,628.21	42.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,540.00	2,610.00	5,930.00	69.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,512.85	8,954.64	10,558.21	54.11
+ GST 7.00/7.00% (S\$)	1,365.90	626.82	739.08	54.11
Nett Amount (S\$)	20,878.75	9,581.46	11,297.29	54.11
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,783.46		

INSPECTION

Date of Assignment: 24/08/2020

Date Inspected: 27/08/2020 Inspected At:

TTS Eurocars Pte Ltd (Sin Ming)
383 Sin Ming Drive, TTS Centre
Singapore 575717

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	801.90 FL	*- FL
2	1		*REAR LH FENDER	Bent	1,891.10 FL	*1,891.10 FL
3	1		*REAR LH DOOR	Bent	1,830.00 FL	*1,830.00 FL
4	1		*FRONT LH DOOR	Bent	1,734.00 FL	*1,734.00 FL
5	1		*FRONT LH FENDER	Repair	789.00 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER	Serviceable	53.76 FL	*- FL
7	1		*BUMPER CLIPS	Not Necessary	59.00 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP	Serviceable	201.00 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP	Serviceable	292.00 FL	*- FL
10	1		*LH ROCKER PANEL	Repair	2,449.00 FL	*- FL
11	1		*REAR LH WHEEL BEARING	Serviceable	454.00 FL	*- FL
12	1		*REAR LH WHEEL HUB (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR LH SHOCK ABSORBER	Serviceable	498.10 FL	*- FL
14	1		*REAR LH SPORTS RIM	Dented	2,106.50 FL	*2,106.50 FL
15	1		*FENDER TAPE	Necessary	24.10 FL	*24.10 FL
16	1		*MOULDING ASSY REAR DOOR FRAME	Necessary	82.50 FL	*82.50 FL
17	1		*FRT DOOR TOP MOULDING LH	Necessary	95.60 FL	*95.60 FL
18	1		*TAPE FRT BLACK REAR LH	Necessary	36.50 FL	*36.50 FL
19	1		*BLACK TAPE REAR DOOR FRT LH	Necessary	36.50 FL	*36.50 FL
20	1		*BLACK TAPE REAR FOOR FRAME REAR LH	Necessary	31.50 FL	*31.50 FL
21	1		*SUNDRIES	Necessary	150.00 FS	*20.00 FS
22	1		*INNER SEAL FOR LH DOOR QUARTER GLASS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,666.06	7,918.30
- List Item Discount on L Items 20.00/20.00% (\$)	2,693.21	1,573.66
Total Parts (\$)	10,972.85	6,344.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING CONNECTION AND CHECK	New	150.00	20.00
2	TUFF KOTE AND SPRAY ANTI RUST PROOFING	New	150.00	90.00
3	SEALANT FOR DOOR PANEL ,FENDER ,END PANEL	New	250.00	90.00
4	TRANSFER FRONT DOOR COMPONENTS ,TRIMS ,SCUFF PLATES	New	250.00	80.00
5	TRANSFER REAR DOOR COMPONENTS ,TRIMS ,SCUFF PLATES	New	250.00	80.00
6	TO REMOVE AND REFIX REAR LH DOOR QUARTER GLASS ,CONDUCT WATER LEAK TEST	New	150.00	30.00
7	SEALANT FOR LH DOOR QUARTER GLASS	New	60.00	60.00
8	TO REMOVE AND REFIX REAR SEATS ,CARPETS ,REAR LH FENDER INNER TRIM ,SPARE TYRE COMPARTMENT BOARDS AND SCUFF PLATES ,SEAT BELTS TO FACILITATE REPAIR	New	250.00	100.00
9	TO REMOVE AND REFIX PETROL TANK ,TO FACILITATE REPAIRS	New	500.00	60.00
10	TO REPLACE REAR LH SPORTS RIM ,CONDUCT WHEEL BALANCING	New	30.00	20.00
11	TO CONDUCT 4 WHEEL ALIGNMENT ,CHECK STEERING ANGLE AND GEOMETRY	New	150.00	80.00
12	TO REMOVE AND REPLACE REAR LH SHOCK ABSORBER WHEEL HUB ,WHEEL BEARING ,LOWER ARM	New	250.00	0.00
13	LABOUR CHARGES TO DISMANTLE & REFIX FRONT BUMPER FRONT LH FENDER ,FRONT LH DOOR ,REAR LH DOOR ,LH ROCKER PANEL ,LH REAR FENDER ,REAR BUMPER TO REPAIR AND ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION	New	2,800.00	1,000.00
14	TO SPRAY PAINT FRONT BUMPER ,FRONT LH FENDER FRONT LH DOOR ,FRONT LH B PILLAR ,LH ROCKER PANEL REAR LH DOOR, REAR LH FENDER ,REAR BUMPER REAR END PANEL AND ALL OTHER ACCIDENT AFFECTED PORTION	New	2,800.00	900.00
15	REMOVE AND REFIX REAR BUMPER SENSOR	New	150.00	0.00
16	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES ,RESTORE PROGRAMME MODULES	New	350.00	0.00
Gross Labour Cost (\$\$)			8,540.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >