

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20008875/AGS3Q2

**Date:** 23/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMR3923T	<b>Insured Vehicle No :</b>	SHC2913S
Date of Loss: 19/08/2020	Nature of Claim: TP	Claim No: MCT20080287

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMR3923T</b>	
Make & Model:	TOYOTA VIOS, 1.5 E CVT (A)	Engine No: 2NR5394754
Reg. Date:	02/01/2020 (Man. Year: 2019)	Chassis No: MR2B23F3201189758
Colour:	Bronze	Odometer: 33984 km
Engine Capacity:	1496 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,021.92	1,505.85	1,516.07	50.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,390.00	860.00	38.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,271.92</b>	<b>2,895.85</b>	<b>2,376.07</b>	<b>45.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,300.00</b>		
<b>(\$\$)</b>	5,271.92	2,300.00	2,971.92	56.37
<b>+ GST 7.00/7.00% (\$\$)</b>	369.03	161.00	208.03	56.37
<b>Nett Amount (\$\$)</b>	<b>5,640.95</b>	<b>2,461.00</b>	<b>3,179.95</b>	<b>56.37</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	24/08/2020	
Date Inspected:	25/08/2020 Inspected At:	F1 Garage (HQ) 8 KAKI BUKIT AVENUE 4, #03-33, PREMIER@KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2020)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMR3923T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	440.10 FL	*440.10 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Necessary	66.10 FL	*66.10 FL
3	1		*REAR BUMPER LH BRACKET	Not Necessary	155.10 FL	*- FL
4	1		*REAR BUMPER LH REFLECTOR ASSY	Cut	107.10 FL	*107.10 FL
5	1		*REAR BUMPER LH REVERSE SENSOR	Not Necessary	321.40 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	459.10 FL	*316.00 FL
7	1		*REAR BUMPER LH SPLASH SHIELD	Not Necessary	78.30 FL	*- FL
8	1		*LH TAILLAMP ASSY	Cracked	422.50 FL	*422.50 FL
9	1		*END PANEL	Dented	821.70 FL	*616.00 FL
10	1		*BOOTLID	Not Necessary	733.36 FL	*- FL
11	1		*BOOTLID CENTRE EMBLEM	Not Necessary	59.10 FL	*- FL
12	1		*BOOTLID VIOS EMBLEM	Not Necessary	72.10 FL	*- FL
13	1		*BOOTLID G EMBLEM	Not Necessary	42.40 FL	*- FL
14	1		*BOOTLID LOCK	Not Necessary	184.20 FL	*- FL
15	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,012.56</b>	<b>1,997.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	990.64	491.95
<b>Total Parts (\$\$)</b>	<b>3,021.92</b>	<b>1,505.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGES ON AFFECTED AREAS	New	900.00	600.00
2	RE-SPRAY ON AFFECTED AREAS	New	1,000.00	600.00
3	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	70.00	50.00
4	REMOVE AND REINSTALL REAR INNER TRIMS AND GARNISH	New	180.00	60.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	50.00	50.00
6	CHECK WIRING AND LIGHTING SYSTEM	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,250.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >