

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 24.08.20

TO : AUTO&GENERAL (BUDGET DIRECT) MOTOR CLAIMS DEPTS
 VEHICLE NO : SMH2387A
 MODEL : HYUNDAI AVANTE
 DATE OF ACCIDENT : 21.08.20
 TIME OF ACCIDENT : 17:20HRS

Verba

KMHD841CMK4845579

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rebond</i>	1	\$ 459.40	\$ 459.40
2	REAR BUMPER MUDFLAP <i>Not in</i>	2	\$ 23.00	\$ 46.00
3	REAR BUMPER LAMP <i>Cracked</i>	2	\$ 201.50	\$ 403.00
4	REAR BUMPER LAMP WIRE HARNESS <i>new</i>	1	\$ 198.30	\$ 198.30
5	REAR BUMPER NUMBER PLATE LAMP <i>new</i>	2	\$ 28.00	\$ 56.00
6	REAR BUMPER CENTRE (BLACK) <i>Rebond</i>	1	\$ 353.50	\$ 353.50
7	REAR BUMPER RETAINER <i>new</i>	2	\$ 29.40	\$ 58.80
8	REAR BUMPER REINFORCEMENT <i>cracked</i>	1	\$ 294.80	\$ 294.80
9	REAR BUMPER REINFORCEMENT BRACKET <i>cracked</i>	3	\$ 19.20	\$ 57.60
10	REAR BUMPER BRACKET <i>new</i>	2	\$ 78.60	\$ 157.20
11	REAR BUMPER SIDE INNER LOWER GARNISH <i>new</i>	2	\$ 37.20	\$ 74.40
12	REAR FENDER INNER COWLING (REAR) <i>new</i>	2	\$ 60.00	\$ 120.00
13	REAR FENDER INNER TRIM <i>Not in</i>	2	\$ 208.00	\$ 416.00
14	TAILLAMP <i>Rt cracked</i>	2	\$ 1,052.10	\$ 2,104.20
15	BOOTLID <i>Dented</i>	1	\$ 1,782.40	\$ 1,782.40
16	BOOTLID LAMP <i>Not in</i>	2	\$ 664.20	\$ 1,328.40
17	BOOTLID LOGO <i>new</i>	1	\$ 54.70	\$ 54.70
18	BOOTLID EMBLEM 'AVANTE' <i>new</i>	1	\$ 31.20	\$ 31.20
19	BOOTLID OUTER SWITCH BUTTON <i>Not in</i>	1	\$ 196.20	\$ 196.20
20	BOOTLID DETECTOR (OUTER) <i>cracked</i>	1	\$ 196.70	\$ 196.70
21	BOOTLID DETECTOR (INNER) <i>Not in</i>	1	\$ 214.80	\$ 214.80
22	BOOTLID REVERSE CAMERA <i>Not in</i>	1	\$ 826.10	\$ 826.10
23	BOOTLID HINGE <i>Not in</i>	2	\$ 94.30	\$ 188.60
24	BOOTLID STOPPER <i>Not in</i>	2	\$ 7.00	\$ 14.00
25	BOOTLID INSULATOR <i>Not in</i>	1	\$ 146.80	\$ 146.80
26	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 116.20	\$ 116.20
27	BOOTLID LOWER LOCK <i>Not in</i>	1	\$ 16.00	\$ 16.00

1052.10 545

TO : AUTO&GENERAL (BUDGET DIRECT) MOTOR CLAIMS DEPTS
 VEHICLE NO : SMH2387A
 MODEL : HYUNDAI AVANTE
 DATE OF ACCIDENT : 21.08.20
 TIME OF ACCIDENT : 17:20HRS

28	BOOTLID WEATHER STRIP <i>lit</i>	1	\$ 92.50	\$ 92.50	✓
29	REAR END PANEL <i>Dented</i>	1	\$ 454.60	\$ 454.60	✓
30	REAR END PANEL TOP GARNISH <i>Replaced</i>	1	\$ 59.80	\$ 59.80	✓
31	REAR FLOOR PANEL TOP BOARD <i>Replaced</i>	1	\$ 219.10	\$ 219.10	✓

5394.10
 4315.28

TOTAL PRICE	\$ 10,737.30
LESS 20%	\$ 2,147.46
SUB TOTAL PRICE	\$ 8,589.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented</i>	1	\$ 80.00	\$ 80.00 50
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 30
3	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 X.
4	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 10
5	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 X.
6	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 X.
7	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 10
8	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 60
9	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 20

360 TOTAL \$ 850.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

TO : AUTO&GENERAL (BUDGET DIRECT) MOTOR CLAIMS DEPTS
VEHICLE NO : **SMH2387A**
MODEL : HYUNDAI AVANTE
DATE OF ACCIDENT : 21.08.20
TIME OF ACCIDENT : 17:20HRS

10	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	60
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 4,600.00

1860

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,439.84
TOTAL LABOUR COST : \$ 4,600.00
TOTAL REPAIR COST : \$ 14,039.84

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian L
1/s 25/08/20
06 Days
total: 6535.28
1/s: 5.2K.

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--