



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2006099
INV Date 07/09/2020
Reference CS/SMO20008893/Usf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 9285J
Insured Veh. GBB 655B
Claim No. CMTD2002416/GPL
Policy No.
Accident Date 18/08/2020
Inspection Date 25/08/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20008893/Usf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 07-09-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 655B	Veh. Inspected	GBJ 9285J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2002416/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	24/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	FEA01BA30055	Colour	WHITE	
Odometer	8084	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/75 R15 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	185/75 R15 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/08/2020	Inspection Date	25/08/2020	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 9285J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR	BADLY DENTED	1,995.00	1,995.00
2	FRONT RH DOOR HINGES @\$185.00	LOWER BENT	370.00	165.00
1	FRONT RH DOOR INNER TRIM BOARD	DEFORMED / CRACKED	1,028.80	671.30
1	FRONT RH DOOR INNER LOCK	DENTED / JAMMED	647.60	488.20
1	FRONT RH DOOR INNER RUBBER	TWISTED	299.00	188.20
1	FRONT RH DOOR INNER LOWER RUBBER	TORN	285.00	285.00
1	FRONT RH DOOR GLASS	SHATTERED	474.00	474.00
1	FRONT RH DOOR GLASS REGULATOR	BENT / TWISTED	1,287.00	566.01
1	FRONT RH DOOR OUTER GARNISH	DISTORTED	315.00	299.20
1	FRONT RH DOOR CHECKER	SERVICEABLE	155.00	-
1	FRONT RH DOOR INNER VENT	DISTORTED	88.00	88.00
1	FRONT RH DOOR PILLAR	BADLY DENTED / BENT	1,423.70	1,423.70
1	FRONT RH CORNER PANEL	WARPED	486.90	486.90
1	FRONT RH CORNER PANEL TOP COVER	NOT NECESSARY	175.80	-
1	FRONT RH HEAD LAMP	CRACKED	672.70	672.70
1	FRONT RH HEAD LAMP PANEL	NO SUCH PARTS	976.00	-
1	FRONT RH SIGNAL LAMP	BROKEN	313.60	313.60
1	FRONT RH SIDE LAMP	BROKEN	213.80	213.80
1	FRONT RH STEP PANEL	NO SUCH PARTS	626.00	-
1	FRONT RH STEP PANEL GARNISH	CRACKED	485.00	485.00
1	FRONT RH STEP PANEL INNER GARNISH	DEFORMED / TWISTED	218.60	218.60
1	FRONT RH WINDSCREEN RUBBER	NOT NECESSARY	473.70	-
1	FRONT RH BRAKE AIR TANK	DENTED	476.00	476.00
1	FRONT RH BUMPER	DISTORTED	1,008.50	1,008.50
1	FRONT RH BUMPER SIDE O/S	DISTORTED	441.70	441.70
1	FRONT RH GRILLE	CRACKED	426.80	426.80
1	FRONT RH "MITSUBISHI" LOGO MOTIF	NECESSARY	186.80	85.80
1	FRONT RH "CANTER" EMBLEM	NECESSARY	75.40	75.40
1	FRONT RH "FUSO" EMBLEM	NECESSARY	163.80	95.00

Report Ref No. CS/SMO20008893/Usf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH POWER STEERING PUMP	CRACKED / JAMMED	1,837.30	1,837.30
	LESS 25% DISCOUNT		-	-3,370.18
			17,626.50	10,110.53
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT RH CORNER PANEL CLIPS (SN)	NOT NECESSARY	28.00	-
1	SET FRONT RH GRILLE CLIPS (SN)	NOT NECESSARY	80.00	-
			108.00	-
	<u>LABOUR</u>			
	REMOVE & REINSTALL DASHBOARD,METER INSTRUMENTS,DISCONNECT WIRING & ETC.		300.00	200.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST.		150.00	60.00
	REMOVE & REPLACE POWER STEERING PUMP & LABOR CHARGE.		80.00	60.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC.		1,200.00	1,000.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		1,400.00	1,000.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	20.00
	TO REMOVE,REPLACE AND TRANSFER DOOR PANEL,FITTING AND MECHANISMS.		120.00	60.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREAS.		100.00	60.00
			3,430.00	2,460.00
GRAND TOTAL			21,164.50	12,570.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CS/SMO20008893/Usf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.