

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMD 20008893/USF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

20/9/20

LTA # 21403

3.18/20 1/5 @ 10,000 confirmed with Subser.

(\$ 11,164.50/RED - 53%)

SOMPO HANDLER - PAU LOONG

Date/Time, File Pass to?

01/09/2020

1) TYPIST

Date/Time, File Return to?

2)

Report Format :

Lump Sum I.B.I: (\$ 10,000.00 L/S)☐

: Preli. Report

☒

: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Veh No:

G9J9285J

Yr Regn:

10 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(Refrigerated)

Make:

mit canter

c.c

2998

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

8084

T/Radio: Insured / Std / NI / NA

Eng/No:

FEA 01BA 30055

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/75-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

R/Bal.

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

18/8/20

D.O.I.

25/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01, Auto Bay @ Kaki Bukit, Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 7310-7310 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBJ9285J200818

Estimate**Customer**

Name: Sompoo Insurance Singapore Private Limited "Without Prejudice" basis
Address: Motor Claims Department No illegal modification(s) is allowed
50 Raffles Place #05-01 / 06 Supplementary item(s) must be resurveyed and
Singapore Land Tower Singapore 048623

Date: 24-08-20**Vehicle No:** GBJ9285J**Model/Make:** Mitsubishi**Canter FEAO1BRISDEK (CBU)****Item No.**

Acknowledged by Repairer

Signature:

Date: **Descriptions Of Parts****Original Quotation / Estimation****Revised Quotation / Cost Of Repair**

1	Front Rh Door	Bally DO	\$ 1,995.00	
2	Door Hinges 02 pcs (@ S\$185.00)	lower 50ft 165.00	\$ 370.00	170
3	Door Inner Trim Board	de/cne	\$ 1,028.80	
4	Door Inner Lock	20/5m	\$ 647.60	
5	Door Inner Rubber	2m	\$ 299.00	
6	Door Inner Lower Rubber	2m	\$ 285.00	
7	Door Glass	shock	\$ 474.00	
8	Door Glass Regulator	Best/2m	\$ 1,287.00	
9	Door Outer Garnish	2.5	\$ 315.00	
10	Door Checker	5m	\$ 155.00	X
11	Door Inner Vent	2.5	\$ 88.00	
12	Door Pillar	Bally DO/2m	\$ 1,423.70	
13	Corner Panel	wo/2m	\$ 486.90	
14	Corner Panel clips 1 set	11	\$ 28.00	SN X
15	Corner Panel Top Cover	11	\$ 175.80	X
16	Head Lamp	cne	\$ 672.70	
17	Head Lamp Panel	NS	\$ 976.00	X
18	Signal Lamp	3.0	\$ 313.60	
19	Side Lamp	3.0	\$ 213.80	
20	Step Panel	NS	\$ 626.00	X
21	Step Panel Garnish	cne	\$ 485.00	
22	Step Panel Inner Garnish	de/2m	\$ 218.60	
23	Windscreen Rubber	11	\$ 473.70	X
24	Brake Air Tank	2.0	\$ 476.00	
25	Bumper	2.5	\$ 1,008.50	
26	Bumper Side	1.5	\$ 441.70	
27	Grille	cne	\$ 426.80	
28	Grille Clips 1 set	11	\$ 80.00	SN X
29	"Mitsubishi" Logo Motif	rec 85.80	\$ 186.80	
30	"Canter" Emblem	rec	\$ 75.40	
31	"FUSO" Emblem	rec 95.00 (252)	\$ 163.80	
32	Power Steering Pump	cne/2m	\$ 1,837.30	
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc		\$ 300.00	200
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test		\$ 150.00	60
	Remove & replace Power Steering Pump & Labor Charge		\$ 80.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 1,200.00	1000
	To putty & spray painting & including touch up paint on accident affected		\$ 1,400.00	1000
	To check all wiring & electrical component for proper function		\$ 80.00	20
	To remove, replace and transfer door panel, fitting and mechanisms		\$ 120.00	60
	To apply Rust Proofing, reseal tuff-coating treatment on accident area		\$ 100.00	60

Total Parts & Labour of estimate for damaged vehicle

\$ 21,164.50

Total amount in Lump Sum Basis for repaired vehicle



Not Authorised
1/5 \$10,000/
25/8/20 7 days.

2.13480.71
252
1011043
1287043
10056