



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5350D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER LOWER TRIM (SN)	SERVICEABLE	558.73	-
1	REAR BUMPER (SN)	CRACKED	1,816.23	1,816.23
1	LH/REAR BUMPER SIDE STABILITY (SN)	SERVICEABLE	41.78	-
2	PARKING SENDER UNIT (SN)	SERVICEABLE	568.84	-
2	PARKTRONIC SENSOR SPACER RING (SN)	NECESSARY	19.54	19.54
1	LH/REAR BUMPER BOTTOM BRACKET (SN) (ADDITIONAL)	CRACKED	22.71	22.71
			3,027.83	1,858.48
	<b><u>LABOUR</u></b>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	960.00
	RESPRAY REAR BUMPER.		1,200.00	600.00
	USING XENTRY DIAGNOSTIC TO CHEKC ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.		120.00	120.00
			3,620.00	2,060.00
	<b>GRAND TOTAL</b>		<b>6,647.83</b>	<b>3,918.48</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,918.48</b>
	<b>LESS EXCESS</b>			<b>-750.00</b>
	<b>NETT LIABILITY</b>			<b>3,168.48</b>

Report Ref No. CS/UOI20008895/R1tf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.