



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101373

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 05/03/2021
Reference CC3/FCI20008897/Kes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 7724T
Insured Veh. SHB 3513L
Claim No. D20003333MFSH
Policy No. D-18088937MFSH
Accident Date 20/08/2020
Inspection Date 21/08/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC3/FCI20008897/Kes3q2	
			Date: 05/03/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3513L	Veh. Inspected	SHB 7724T	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D20003333MFSH	Excess (\$)	0.00	
Assign From	MERINA	Assign Date	21/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU303081296	Colour	M.P. WHITE / RED	
Odometer	94969 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	SAILUN	9 mm	
L/H Front Tyre	195/60 R15	SAILUN	9 mm	
R/H Rear Tyre	195/60 R15	SAILUN	9 mm	
L/H Rear Tyre	195/60 R15	SAILUN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2020	Inspection Date	21/08/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7724T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	516.00	516.00
1	BRACKET,FRONT BUMPER EXTENSION MOUNTING	SERVICEABLE	103.40	-
1	REINFORCEMENT,FRONT BUMPER	BENT	716.60	716.60
1	REINFORCEMENT,FRONT BUMPER,NO 2	BENT	246.10	246.10
1	COVER,FRONT BUMPER HOLE,RH	MISSING	29.30	29.30
1	COVER,FRONT BUMPER HOLE,LH	SERVICEABLE	29.30	-
1	ABSORBER,FRONT BUMPER LOWER	CRACKED	132.70	132.70
1	ABSORBER,FRONT BUMPER ENERGY	CRACKED	79.60	79.60
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	80.10	80.10
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	82.30	-
1	COVER,ENGINE UNDER,NO 1	SERVICEABLE	472.40	-
1	COVER SUB-ASSY,ENGINE UNDER,NO 2	SERVICEABLE	241.90	-
1	EXTENSION,FRONT BUMPER RH	TO REPAIR SEE LABOUR	120.10	-
1	EXTENSION,FRONT BUMPER LH	TO REPAIR SEE LABOUR	120.10	-
1	FRONT LED LAMP (LOWER) RH	SERVICEABLE	951.40	-
1	FRONT LED LAMP (LOWER) LH	SERVICEABLE	951.40	-
1	FRONT HEADLAMP RH	MTG CRACKED	2,637.60	2,637.60
1	COMPUTER SUB-ASSY,HEADLAMP RH NO 1	SERVICEABLE	960.50	-
1	MOTOR,HEADLAMP LEVELING,RH	SERVICEABLE	487.50	-
1	FRONT HEADLAMP LH	SERVICEABLE	2,637.60	-
1	COMPUTER SUB-ASSY,HEADLAMP LH NO 1	SERVICEABLE	960.50	-
1	FRONT FENDER RH	BUCKLED	977.80	977.80
1	LINER,FRONT FENDER RH	SERVICEABLE	206.70	-
1	EMBLEM,SIDE PANEL	NECESSARY	54.60	54.60
1	GRILLE SUB-ASSY,RADIATOR	CRACKED	346.00	346.00
1	GRILLE RADIATOR,LOWER NO 1	CRACKED	170.10	170.10
1	EMBLEM ASSY,RADIATOR GRILLE	MISSING	90.80	90.80
1	FRONT BONNET	BENT	983.10	983.10
1	HINGE ASSY,HOOD,RH	TO REPAIR SEE LABOUR	58.90	-

Report Ref No. CC3/FCI20008897/Kes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HINGE ASSY,HOOD,LH	TO REPAIR SEE LABOUR	58.90	-
1	INSULATOR,HOOD	SERVICEABLE	410.90	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	977.80	-
1	LINER,FRONT FENDER,LH	SERVICEABLE	202.50	-
1	EMBLEM,SIDE PANEL	NOT NECESSARY	54.60	-
1	COVER,RADIATOR SUPPORT OPENING	SERVICEABLE	235.30	-
1	WIRE,ENGINE ROOM MAIN	SERVICEABLE	7,323.90	-
1	SUPPORT SUB-ASSY,RADIATOR,RH	SERVICEABLE	245.10	-
1	SUPPORT SUB-ASSY,RADIATOR,UPPER	SERVICEABLE	377.10	-
1	SUPPORT SUB-ASSY,RADIATOR,LOWER	SERVICEABLE	409.90	-
1	SUPPORT SUB-ASSY,RADIATOR,LH	SERVICEABLE	245.10	-
1	SUPPORT,RADIATOR,UPPER RH	TO REPAIR SEE LABOUR	78.90	-
1	SUPPORT,RADIATOR,UPPER LH	TO REPAIR SEE LABOUR	78.90	-
1	JAR ASSY,WINDSHIELD WASHER	SERVICEABLE	219.10	-
1	INLET SUB ASSY,WASHER	SERVICEABLE	67.00	-
1	MOTOR AND PUMP ASSY,WINDSHIELD WASHER	SERVICEABLE	292.40	-
1	GUIDE RADIATOR AIR,NO 3	SERVICEABLE	112.70	-
1	GUIDE RADIATOR AIR,NO 1 RH	SERVICEABLE	65.30	-
1	SEAL RADIATOR TO SUPPORT,NO 2	SERVICEABLE	29.60	-
1	GUIDE,RADIATOR AIR NO 1 LH	SERVICEABLE	69.90	-
1	SEAL RADIATOR TO SUPPORT,NO 3	SERVICEABLE	29.60	-
1	HORN ASSY,HIGH PITCHED	DENTED	134.80	134.80
1	PANEL SUB ASSY,FRONT DOOR,RH	TO REPAIR SEE LABOUR	1,300.70	-
1	TAPE,BLACK OUT,NO 1 FRT RH	NOT NECESSARY	13.30	-
1	TAPE,BLACK OUT,NO 2 FRT RH	NOT NECESSARY	43.50	-
1	TAPE,BLACK OUT,NO 3 FRT RH	NOT NECESSARY	26.30	-
1	INLET,AIR CLEANER,NO 3	NOT NECESSARY	42.10	-
1	INLET,AIR CLEANER,NO 2	SERVICEABLE	112.70	-
1	INLET,AIR CLEANER,NO 1	SERVICEABLE	155.60	-

Report Ref No. CC3/FCI20008897/Kes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEAL,HOOD TO FRONT END PANEL	TO REPAIR SEE LABOUR	51.60	-
1	BATTERY	SERVICEABLE	1,584.90	-
1	CLAMP SUB-ASSY,BATTERY	TO REPAIR SEE LABOUR	115.50	-
	LESS 25% DISCOUNT		-7,652.48	-1,798.80
			22,957.42	5,396.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL RIM (SN)	SERVICEABLE	1,879.40	-
1	FRONT WHEEL RIM COVER (SN)	SERVICEABLE	211.50	-
1	FRONT TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-
1	SET CLIP,FRONT LH FENDER LINER (SN)	NOT NECESSARY	65.00	-
1	SET CLIP,FRONT RH FENDER LINER (SN)	NOT NECESSARY	65.00	-
1	FRONT NUMBER PLATE (SN)	MISSING	200.00	45.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	80.00	80.00
1	SET FRT LH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRT RH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	60.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	100.00	-
1	ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	65.00	-
1	HOOD INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	50.00	-
			3,235.90	125.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF EXTENSION,FRONT BUMPER RH,EXTENSION,FRONT BUMPER LH,HINGE ASSY,HOOD,RH,HINGE ASSY,HOOD,LH,FRONT FENDER LH,SUPPORT,RADIATOR,UPPER RH,SUPPORT,RADIATOR,UPPER LH,PANEL SUB ASSY,FRONT DOOR,RH,SEAL,HOOD TO FRONT END PANEL AND CLAMP SUB-ASSY,BATTERY.		2,000.00	500.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,000.00	660.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	350.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TOWING FEES.		170.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT BATTERY, BATTERY COVER, ELECTRICAL WIRING, FUSE BOX, RELAY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-
			7,080.00	1,260.00
GRAND TOTAL			33,273.32	6,781.40

RECOMMENDED COST OF REPAIRS				6,781.40
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/FCI20008897/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 7724T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 7724T

RE-INSPECTION

