

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008907/KEA3Q2
Date: 18/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100423019
Claimant Vehicle No :	SLD6282A	Insured Vehicle No :	SY7345C
Date of Loss:	17/08/2020	Nature of Claim:	TP
		Claim No:	7367117713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD6282A		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 G (A)	Engine No:	2NR8528565
Reg. Date:	23/06/2016 (Man. Year: 2015)	Chassis No:	NRE1610011462
Colour:	Metallic Green	Odometer:	54053 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,839.30	8,102.25	16,737.05	67.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,520.00	1,060.00	29.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,419.30	10,622.25	17,797.05	62.62
Approved Total (Overridden) (S\$)		8,500.00		

(S\$)	28,419.30	8,500.00	19,919.30	70.09
+ GST 7.00/7.00% (S\$)	1,989.35	595.00	1,394.35	70.09
Nett Amount (S\$)	30,408.65	9,095.00	21,313.65	70.09
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		9,895.00		

INSPECTION

Date of Assignment: 24/08/2020

Date Inspected: 24/08/2020

Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
 Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117
 Singapore 575636

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	531.00 F	*531.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	5.50 F	*5.50 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	343.00 F	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	58.00 F	*58.00 FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	58.00 F	*58.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	340.00 F	*- FL
7	1		*FRONT BUMPER FOG LAMP LH (NPA)	Not Necessary	0.00 F	*- FL
8	1		*FRONT BUMPER FOG LAMP RH (NPA)	Not Necessary	0.00 F	*- FL
9	1		*FRONT BUMPER FOG LAMP COVER LH	Serviceable	49.00 F	*- FL
10	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	49.00 F	*- FL
11	1		*FRONT BUMPER SPONGE	Serviceable	79.00 F	*- FL
12	1		*FRONT BUMPER UNDER COVER	Serviceable	198.00 F	*- FL
13	1		*FRONT GRILLE	Scratched	395.00 F	*395.00 FL
14	1		*FRONT GRILLE CLIPS	Necessary	5.50 F	*5.50 FL
15	1		*FRONT GRILLE BADGE (NPA)	Not Necessary	0.00 F	*- FL
16	1		*FRONT GRILLE BACKING (NPA)	Not Necessary	0.00 F	*- FL
17	1		*FRONT FENDER LH	Bent	676.00 F	*676.00 FL
18	1		*FRONT FENDER LINING /SHIELD LH	Cracked	171.00 F	*171.00 FL
19	1		*FRONT FENDER LINING /SHIELD CLIPS	Necessary	5.90 F	*5.90 FL
20	1		*FRONT FENDER RH	Bent	676.00 F	*676.00 FL
21	1		*FRONT FENDER LINING /SHIELD RH	Distorted	171.00 F	*171.00 FL
22	1		*FRONT FENDER LINING /SHIELD CLIPS	Necessary	5.90 F	*5.90 FL
23	1		*FRONT PILLAR OUTER GARNISH	Missing	85.00 F	*85.00 FL
24	1		*FRONT SUPPORT PANEL ASSY	Bent	919.00 F	*919.00 FL
25	1		*RADIATOR AIR DEFLECTOR LH	Serviceable	125.00 F	*- FL
26	1		*RADIATOR AIR DEFLECTOR RH	Serviceable	125.00 F	*- FL
27	1		*A/C CONDENSER	Serviceable	1,298.00 F	*- FL
28	1		*A/C PIPES (SUCTION)	Serviceable	385.00 F	*- FL
29	1		*A/C PIPES (DISCHARGE)	Serviceable	399.00 F	*- FL
30	1		*RADIATOR	Serviceable	1,698.00 F	*- FL
31	1		*RADIATOR TOP BRACKET LH	Repair	25.00 F	*- FL
32	1		*RADIATOR TOP BRACKET RH	Repair	25.00 F	*- FL
33	1		*RADIATOR LOWER BUSH	Serviceable	28.00 F	*- FL
34	1		*HEADLAMP LH	Mtg Cracked	607.00 F	*607.00 FL
35	1		*HEADLAMP RH	Mtg Cracked	607.00 F	*607.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*HEADLAMP PANEL LH	Bent	128.00 F	*128.00 FL
37	1		*HEADLAMP PANEL RH	Repair	128.00 F	*- FL
38	1		*FRONT FENDER SIGNAL LAMP LH	Missing	55.00 F	*55.00 FL
39	1		*FRONT FENDER SIGNAL LAMP RH	Serviceable	55.00 F	*- FL
40	1		*SIDE SKIRT LH	No such part	148.00 F	*- FL
41	1		*SIDE SKIRT RH	No such part	148.00 F	*- FL
42	1		*FRONT WHEEL RIM LH (NPA)	Serviceable	0.00 F	*- FL
43	1		*FRONT WHEEL RIM RH (NPA)	Serviceable	0.00 F	*- FL
44	1		*FRONT DOOR LH	Repair	1,100.00 F	*- FL
45	1		*SIDE MIRROR COVER LH	Dented	74.00 F	*74.00 FL
46	1		*SIDE MIRROR COVER LH	Serviceable	74.00 F	*- FL
47	1		*FRONT DOOR HANDLE LH (COMPLETE SET)	Serviceable	340.00 F	*- FL
48	1		*BONNET	Bent	720.00 F	*720.00 FL
49	1		*BONNET HINGE LH	Distorted	57.00 F	*57.00 FL
50	1		*FENDER BRACKET LH (NPA)	Not Necessary	0.00 F	*- FL
51	1		*HEAD LAMP PANEL LH	Not Necessary	98.00 F	*- FL
52	1		*BUMPER FORM	Serviceable	79.00 F	*- FL
53	1		*BIMPER SIDE CLIP	Repeated	5.50 F	*- FL
54	1		*WIPER TOP GARNISH LH (NPA)	Not Necessary	0.00 F	*- FL
55	1		*ENGINE CROSS MEMBER	Bent	1,824.00 F	*1,754.20 FL
56	1		*UNDERCARRIAGE LOWER ARM LH	Distorted	1,033.00 F	*489.50 FL
57	1		*UNDERCARRIAGE LOWER ARM RH	Distorted	1,033.00 F	*489.50 FL
58	1		*ABSORBER LB	Bent	421.00 F	*421.00 FL
59	1		*ABSORBER RH	Bent	421.00 F	*421.00 FL
60	1		*KNUCKLE	Bent	495.00 F	*495.00 FL
61	1		*KNUCKLE BEARING	Necessary	158.00 F	*158.00 FL
62	1		*STABALISER	Distorted	385.00 F	*385.00 FL
63	1		*STABALISER LINK	Distorted	179.00 F	*179.00 FL
64	1		*STABALISER BUSH	Serviceable	35.00 F	*- FL
65	1		*DRIVE SHAFT RH	Repair	977.00 F	*- FL
66	1		*ABS SENSORS LH	Serviceable	298.00 F	*- FL
67	1		*ABS SENSORS RH	Serviceable	298.00 F	*- FL
68	1		*HARDNESS WIRE	Repair	3,930.00 F	*- FL
69	1		*TIE ROD (NPA)	Not Necessary	0.00 F	*- FL
70	1		*TYRES RH (NPA)	Not Necessary	0.00 F	*- FL
71	1		*TYRES RIM RH (NPA)	Not Necessary	0.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	24,839.30	10,803.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	2,700.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					24,839.30	8,102.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE ADDITIONAL LABOR CHARGE TO UNDERCARRIAGE PARTS CHANGES	New	500.00	240.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS (FRONT)	New	1,500.00	1,100.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATE (FRONT)	New	1,200.00	1,100.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECH ELECTRICAL WIRING	New	80.00	20.00
5	PROVIDE SKILL LABOUR TO WHEEL ALIGNMENT	New	150.00	60.00
6	PROVIDE SKILL LABOUR FOR UNDERCARRIAGE (FRONT)	New	150.00	0.00
Gross Labour Cost (S\$)			3,580.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >