

19/211/BE

Allied

Auto Appraisal

Our Reference : 19/0019/TP
Invoice Number : 1516

Date: 16 March 2019

M/s Black Eagle Rental LLP
25 Kaki Bukit Road 4
#05-57 Synergy @ KB
Singapore 417800

INVOICE

DESCRIPTION	AMOUNT S\$
Professional Inspection Fee (SKA 7103 E)	\$260.00
Coloured Photographs (15 pieces)	\$15.00
Transport Fee	\$60.00
Re-inspection Fee (12/03/2019)	\$80.00
TOTAL	\$415.00

Terms of payment: Cash on delivery
All payments payable to "Allied Auto Appraisal"



Allied Auto Appraisal

Allied Auto Appraisal
443 Ang Mo Kio Avenue 10 ■ #11-1225 ■ Singapore 560443
■ Email: alliedauto@ymail.com
Company Registration No. : 53127785B

Allied

Auto Appraisal

Our Ref : 19/0019/TP
Your Ref : Not Advised

Date: 8 March 2019

M/s Black Eagle Rental LLP
25 Kaki Bukit Road 4
#05-57 Synergy @ KB
Singapore 417800

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT (WITHOUT PREJUDICE)

Detailed accounts of our inspection are as follows:

(1) REFERENCE

Name of Claimant	: M/s Black Eagle Rental LLP	Date of Request	: 8 March 2019
Policy Number	: 5098750063 drivo CLASSIC	Referred By	: Insured
Claim Number	: Not Advised	Date of Inspection	: 8 March 2019
Accident Date	: 25 January 2019	Date of Re-inspection	: 12 March 2019
Repairer	: Black Eagle Auto Pte Ltd	Sum Insured	: Not Applicable
	25 Kaki Bukit Road 4	Excess Amount	: Not Applicable
	#05-80 Synergy @ KB	3 rd Party Vehicle	: SLP 4121 G
	Singapore 417800	3 rd Party Insurer	: FWD Singapore Pte Ltd

(2) PARTICULARS OF VEHICLE

Registration Number	: SKA 7103 E	Mileage	: 164,980 km
Make & Model	: Toyota Wish 1.8X A	Chassis Number	: ZGE200008634
Date of Registration	: 25 March 2011	Engine Number	: 2ZR0428472
Colour	: Black	Engine Capacity	: 1,797 cc


(3) PRE-ACCIDENT CONDITION (STATIC TEST ONLY)

Steering	: In order	Paint Work	: Good
Foot-brake	: In order	Modification	: Nil
Hand-brake	: In order	General Condition	: Good

(4) TYRE CONDITION

	Remaining Thread Depth (%)	Make	Size
Front right tyre	50%	Bridgestone	195/65R15
Front left tyre	40%	Maxxis	195/65R15
Rear right tyre	60%	Bridgestone	195/65R15
Rear left tyre	60%	Bridgestone	195/65R15

(5) POINT OF IMPACT



(6) GENERAL DESCRIPTION OF DAMAGES

The impact of the collision has damaged/affected the right rear door, right rocker garnish and etc.

Please refer to the Annex for a detailed account of the damages and photographs taken.

(7) RECOMMENDATION

We have inspected thoroughly the actual damages found on the vehicle before we conclude as to whether the parts needed replacement or repairs. The estimated cost of repair submitted by the repairer is **\$3,873.62**. We have adjusted the cost to **\$3,593.62** and recommend that the repairs to be taken on a lump sum basis of **\$3,050.00**. In our opinion, the damaged parts are consistent with that caused by the accident.

(8) REMARKS

We have not authorised the repairs. However, for information, under normal circumstances, the period of repair should not exceed 4 working days.

This inspection was conducted on a "**Without Prejudice**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report and photographs.

Allied Auto Appraisal



H. C. Ng
Motor Vehicle Appraiser

ANNEX

REPAIR DETAILS (SKA 7103 E)

Recommended Parts

No	Qty	Particulars	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear Door Assembly - O/s	Dented/Grazed	1,663.20	1,663.20
2	1	Rear Door Black Tape - O/s	Necessary	47.30	47.30
3	1	Rear Door Weather-strip - O/s	Clip Snapped	196.90	196.90
4	1	Rocker Panel Garnish - O/s	Deep Grazed	1,244.10	1,244.10
				3,151.50	3,151.50
			Less 25%	787.88	787.88
			Sub-Total	2,363.62	2,363.62
		<u>Special Nett Item</u>			
5	1	Rear Door Inner Sealer - O/s	Necessary	80.00	60.00
		Total Parts (S\$)		2,443.62	2,423.62

Recommended Labours

No	Particulars	Repairer's Amount	Adjuster's Amount
1	To remove/install right rear accident damaged parts to replace, re-align and adjust if necessary.	600.00	450.00
2	To transfer right rear door locking mechanism and other components to new door panel include checking components for function.	150.00	120.00
3	To putty and re-spray painting on right rear door and right rocker panel garnish.	600.00	560.00
4	Rust-proofing on the right rear accident affected portion.	80.00	40.00
	Total Labour (S\$)	1,430.00	1,170.00
	Total Repair Cost (S\$)	3,873.62	3,593.62

Adjusted Repair Cost (Lump sum basis)

S\$3,050.00









