

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20008917/EGA3Q2

**Date:** 25/09/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMG5902Z	<b>Insured Vehicle No :</b>	SHC3023D
Date of Loss: 17/08/2020	Nature of Claim: TP	Claim No: MCT20080240

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG5902Z		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4871929
Reg. Date:	24/03/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106142119
Colour:	Black	Odometer:	170547 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Silverstone 4 mm	Rear Left Side:	Silverstone 4 mm
Front Right Side:	Silverstone 4 mm	Rear Right Side:	Silverstone 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,143.60	476.40	3,667.20	88.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	760.00	2,100.00	73.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,003.60</b>	<b>1,236.40</b>	<b>5,767.20</b>	<b>82.35</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>950.00</b>		
<b>Nett Amount (\$\$)</b>	<b>7,003.60</b>	<b>950.00</b>	<b>6,053.60</b>	<b>86.44</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	24/08/2020	
Date Inspected:	25/08/2020 Inspected At:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2020)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG5902Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER INNER SPONGE	Not Necessary	135.90 F	*- FL
2	1		*FRONT BUMPER SIDE RETAINERS	Broken	145.20 F	*145.20 FL
3	1		*FRONT FENDER INNER SHIELD	Serviceable	426.50 F	*- FL
4	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	186.00 F	*- FL
5	1		*FRONT BUMPER	Broken	1,220.00 F	*490.00 FL
6	1		*HEADLAMP RH	*Check	950.00 F	*- FL
7	1		*FRONT LEFT PASSENGER RIM	Serviceable	420.00 F	*- FL
8	1		*FRONT R/H FENDER	Serviceable	660.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,143.60</b>	<b>635.20</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>158.80</b>
<b>Total Parts (\$\$)</b>	<b>4,143.60</b>	<b>476.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO ESTABLISH MIRROR MOTOR & RESET WIRING FOCUSSING	New	210.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMPS FOCUSSING	New	320.00	30.00
3	TO APPLY TUFF KOTE	New	330.00	30.00
4	PANEL BEATING	New	1,000.00	300.00
5	TO SAND-DOWN ,PATCH-WORK ,RE-SPRAY PAINT	New	1,000.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,860.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >