

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008919/T1RA3Q2
Date: 07/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900005296
Claimant Vehicle No :	SHB3311C	Insured Vehicle No :	SBL69R
Date of Loss:	24/08/2020	Nature of Claim:	TP
		Claim No:	2877509163SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3311C		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU388836
Reg. Date:	16/01/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU184118
Colour:	Yellow	Odometer:	45724 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	387.12	387.12	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	1,030.00	330.00	24.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,747.12	1,417.12	330.00	18.89
+ GST 7.00/7.00% (S\$)	122.30	99.20	23.10	18.89

Nett Amount (S\$)	1,869.42	1,516.32	353.10	18.89
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (S\$)		156.49		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,799.81		

INSPECTION

Date of Assignment: 24/08/2020

Date Inspected: 24/08/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL CAP (LH)	Cut	346.40 FL	*346.40 FL
2	1		*REAR DOOR APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
3	1		*FUEL LID	Necessary	30.00 FS	*30.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	456.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	69.28
					Total Parts (S\$)	387.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING -REAR DOOR LH ETC	New	300.00	300.00
2	SPRAY PAINTING CHARGE-REAR BUMPER ,ROCKER PANEL GARNISH LH & REAR FENDER LH ETC	New	1,000.00	700.00
3	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			1,360.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >