

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008923/T1RA3Q2
Date: 20/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070100072
Claimant Vehicle No :	SHC1291J	Insured Vehicle No :	SLL9848G
Date of Loss:	21/08/2020	Nature of Claim:	TP
		Claim No:	0989537818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1291J		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU400255
Reg. Date:	18/03/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU187414
Colour:	Blue	Odometer:	34571 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,050.36	1,788.92	261.44	12.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	610.00	570.00	48.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,230.36	2,398.92	831.44	25.74
+ GST 7.00/7.00% (S\$)	226.13	167.92	58.21	25.74

Nett Amount (\$\$)	3,456.49	2,566.84	889.65	25.74
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Car Rental (3.0 x S\$129.47/day) (\$\$)		388.41		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,107.25		
Global Sum Settlement (\$\$)		3,050.00		

INSPECTION

Date of Assignment: 24/08/2020

Date Inspected: 24/08/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
4	2		*REAR REINFORCEMENT STAY LH/RH	Bent	276.20 FL	*276.20 FL
5	2		*REAR BUMPER SIDE BRACKET LH/RH	Not Necessary	111.60 FL	*- FL
6	10		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
7	1		*REAR BUMPER COVER TOWING	Not Necessary	98.80 FL	*- FL
8	1		*REAR BUMPER FOG LAMP	Cracked	201.50 FL	*201.50 FL
9	1		*REAR BUMPER REFLECTOR	Not Necessary	31.90 FL	*- FL
10	1		*REAR BUMPER MOULDING LOW CT	Deformed	125.00 FL	*125.00 FL
11	1		*ANTENNA SMART KEY	Cracked	140.50 FL	*140.50 FL
12	1		*REAR REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
13	1		*REAR NUMBER PLATE /WITH HOLDER	Cracked	50.00 FS	*50.00 FS
14	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,492.95	2,178.65
- List Item Discount on L Items 20.00/20.00% (\$)	442.59	389.73
Total Parts (\$)	2,050.36	1,788.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	580.00	320.00
2	SPRAY PAINTING CHARGE	New	420.00	200.00
3	TUFF KOTE	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
5	TOWING FEE	New	60.00	60.00
Gross Labour Cost (S\$)			1,180.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >