

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008925/ERA3Q2
Date: 24/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070012083
Claimant Vehicle No :	SLG6078H	Insured Vehicle No :	SCU819J
Date of Loss:	19/08/2020	Nature of Claim:	TP
		Claim No:	6946240366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6078H	Engine No:	R16A12000996
Make & Model:	HONDA CIVIC, 1.6 L VTI (A)	Chassis No:	JHMFD46207S200478
Reg. Date:	07/06/2007 (Man. Year: 2007)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,005.04	3,882.96	6,122.08	61.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,320.00	1,080.00	45.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,405.04	5,202.96	7,202.08	58.06
Approved Total (Overridden) (S\$)		4,150.00		
Nett Amount (S\$)	12,405.04	4,150.00	8,255.04	66.55
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,577.49		

INSPECTION

Date of Assignment:	24/08/2020		
Date Inspected:	25/08/2020	Inspected At:	Mcgap Workshop (HQ) 6 Jalan Lam Huat, Carros Centre #05-68 Singapore 737869
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	988.00 FL	*638.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	326.30 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Broken	112.60 FL	*112.60 FL
4	1		*FRONT BUMPER SIDE GRILLE RH	Not Necessary	159.00 FL	*- FL
5	1		*FRONT BUMPER LOWER CENTRE GRILLE	Not Necessary	211.00 FL	*- FL
6	1		*FRONT BUMPER UNDERCOVER	Not Necessary	312.00 FL	*- FL
7	1		*FRONT GRILLE	Broken	498.00 FL	*498.00 FL
8	1		*HEADLAMP RH	Broken	1,169.40 FL	*1,169.40 FL
9	1		*HEADLAMP LOWER BRACKET RH	Bent	72.80 FL	*72.80 FL
10	1		*FRONT FENDER RH	Dented	698.00 FL	*698.00 FL
11	1		*FRONT FENDER INNER PANEL RH	Not Necessary	398.00 FL	*- FL
12	1		*FRONT FENDER BRACKET RH	Not Necessary	58.60 FL	*- FL
13	1		*FRONT FENDER UPPER GARNISH RH	Not Necessary	158.00 FL	*- FL
14	1		*FRONT FENDER COWLING RH	Torn	185.20 FL	*185.20 FL
15	1		*FRONT SUPPORT PANEL	Not Necessary	542.00 FL	*- FL
16	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	312.00 FL	*- FL
17	1		*RADIATOR COOLANT RESERVOIR	Not Necessary	212.00 FL	*- FL
18	1		*FUSE BOX	Not Necessary	784.00 FL	*- FL
19	1		*FRONT KNUCKLE ARM RH	Bent	490.50 FL	*385.00 FL
20	1		*FRONT KNUCKLE BEARING RH	Jammed	198.20 FL	*198.20 FL
21	1		*FRONT LOWER ARM RH	Not Necessary	473.90 FL	*- FL
22	1		*FRONT STABILIZER LINK RH	Not Necessary	187.60 FL	*- FL
23	1		*FRONT SHOCK ABSORBER RH	Bent	512.20 FL	*334.00 FL
24	1		*STEERING RACK AND PINION	Not Necessary	1,897.00 FL	*- FL
25	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT SPORT RIM RH	Cut	800.00 FS	*400.00 FS
27	1		*FRONT TYRE RH	Not Necessary	280.00 FS	*- FS
28	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*20.00 FS
29	1		*RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,196.30	4,741.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,191.26	858.24
Total Parts (\$\$)	10,005.04	3,882.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	600.00
2	PANEL BEATING ON AFFECTED AREAS	New	800.00	400.00
3	CONDUCT FULL WHEEL ALIGNMENT	New	120.00	60.00
4	REMOVE AND REFIT FRONT UNDERCARRIAGE	New	400.00	200.00
5	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$\$)			2,400.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >