

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008933/GVF3E2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900099542
Claimant Vehicle No : XB87E	Insured Vehicle No :	SML7647X
Date of Loss: 20/08/2020	Nature of Claim: TP	Claim No: 6201916101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XB87E	Engine No:	6D24341872
Make & Model:	mitsubishi FV517JD2RDEB, 11.9 D (M)	Chassis No:	FV517JA00421
Reg. Date:	01/04/2004 (Man. Year: 2003)	Odometer:	64568 km
Colour:	White		
Engine Capacity:	11945 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	11.00-20	Rear Tyre Size:	11.00-20 (D)
Front Left Side:	F.M. SLEEK 6 mm	Rear Left Side:	F.M. SLEEK 6/6 mm
Front Right Side:	F.M. SLEEK 6 mm	Rear Right Side:	F.M. SLEEK 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	24/08/2020	Inspected At:	Mje Motor
Date Inspected:	03/09/2020		BLK 7 SIN MING IND EST SEC C
			#01-96 SINGAPORE 575642
Estimated Period of Repair:	1.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER	Repair	0.00 F	*- F	
2	1		*FRT CORNER PANEL	Repair	0.00 F	*- F	
3	1		*FRT LH DOOR	Repair	0.00 F	*- F	
4	1		*FRT WHEEL ARCH PANEL	Repair	0.00 F	*- F	
5	1		*FRT WHEEL ARCH PANEL GARNISH	Cut	0.00 F	*- F	
6	1		*FRT STEP PANEL	Cut	0.00 F	*- F	
7	1		*FRT STEP PANEL INNER GARNISH	Cracked	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >