

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20008935/AVF3E2

Date: 29/12/2020

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC20B00001501
Claimant Vehicle No : SFQ8T Insured Vehicle No : SJW1828H
Date of Loss: 18/08/2020 Nature of Claim: TP Claim No: DMPC2000131H/NC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFQ8T**
Make & Model: AUDI A1, 1.4 TFSI S-TRONIC (185BHP) (A) Engine No: CYR063552
Reg. Date: 18/06/2018 (Man. Year: 2018) Chassis No: WAUZZZ4M0JD042853
Colour: White Odometer: 23537 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/35 R22 Rear Tyre Size: 295/35 R22
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,358.00	3,610.10	16,747.90	82.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,822.00	2,472.00	1,350.00	35.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,180.00	6,082.10	18,097.90	74.85
+ GST 7.00/7.00% (S\$)	1,692.60	425.75	1,266.85	74.85
Nett Amount (S\$)	25,872.60	6,507.85	19,364.75	74.85

INSPECTION

Date of Assignment: 25/08/2020
Date Inspected: 27/08/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2020)
Parts: 144	AUDI A1 1.4 TFSI S-TRONIC (185BHP) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFQ8T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Damaged	2,434.00 FS	*2,434.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	442.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	66.00 FS	*- FS
4	1		*FRONT BUMPER END CAP - LH	Not Necessary	35.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	273.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	203.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	797.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	208.00 FS	*- FS
9	1		*FRONT SPOILER - LH	Deformed	137.00 FS	*137.00 FS
10	1		*FRONT SPOILER - LH OUTER	Not Necessary	43.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	2,445.00 FS	*- FS
12	1		*RADIATOR GRILLE COVER	Not Necessary	72.00 FS	*- FS
13	1		*RADIATOR GRILLE INNER COVER	Not Necessary	61.00 FS	*- FS
14	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Deformed	294.00 FS	*293.50 FS
15	1		*FRONT BUMPER END CAP - LH	Damaged	33.00 FS	*32.60 FS
16	1		*RADIATOR GRILLE SPOILER - LH	Not Necessary	57.00 FS	*- FS
17	1		*FRONT BUMPER CARRIER	Not Necessary	858.00 FS	*- FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	170.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	72.00 FS	*- FS
20	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS
21	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	0.00 FS	*- FS
22	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
23	1		*LED HEADLIGHT - LH	Not Necessary	9,813.00 FS	*- FS
24	1		*LIFT CYLINDER - LH	Not Necessary	196.00 FS	*- FS
25	1		*WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
26	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
27	2		*FRONT WHEEL COVER - LH / RH	Necessary	654.00 FS	*653.00 FS
28	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
29	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,358.00 3,610.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	450.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,350.00	900.00
4	TO RESPRAY FRONT BUMPER	New	1,350.00	900.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (S\$)	3,822.00
				2,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >