

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008939/R1QF3Q2

**Date:** 25/11/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00048312000
<b>Claimant Vehicle No :</b>	GBE6552J	<b>Insured Vehicle No :</b>	GBC1792B
Date of Loss:	28/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202895/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6552J	Engine No:	K9KC400D055223
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	VSKYBAM20Z0120924
Reg. Date:	19/02/2016 (Man. Year: 2015)	Odometer:	186339 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70R14C	Rear Tyre Size:	175/70R14C
Front Left Side:	NOVA-FORCE 6 mm	Rear Left Side:	NOVA-FORCE 6 mm
Front Right Side:	NOVA-FORCE 6 mm	Rear Right Side:	NOVA-FORCE 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,034.70	1,887.10	3,147.60	62.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,450.00	690.00	32.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,174.70</b>	<b>3,337.10</b>	<b>3,837.60</b>	<b>53.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,174.70</b>	<b>2,650.00</b>	<b>4,524.70</b>	<b>63.06</b>

### INSPECTION

Date of Assignment:	26/08/2020	
Date Inspected:	25/08/2020 Inspected At:	Skylink Auto Garage Pte Ltd (HQ) BLK 48 TOH GUAN ROAD EAST #02-127, ENTERPRISE HUB, SINGAPORE 608586 Singapore 608586
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 Nov 2020)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE6552J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BACK DOOR ASSY LH	Bent	1,200.00 FL	*1,200.00 FL
2	1		*BACK DOOR HINGE UPPER LH	Serviceable	65.00 FL	*- FL
3	1		*BACK DOOR HINGE LOWER LH	Serviceable	65.00 FL	*- FL
4	1		*BACK DOOR ASSY RH	Serviceable	1,100.00 FL	*- FL
5	1		*BACK DOOR HINGE UPPER RH	Serviceable	65.00 FL	*- FL
6	1		*BACK DOOR HINGE LOWER RH	Serviceable	65.00 FL	*- FL
7	1		*BACK DOOR OUTER MOULDING	Serviceable	210.00 FL	*- FL
8	1		*REAR NUMBER PLATE LIGHT LH	Serviceable	75.00 FL	*- FL
9	1		*REAR NUMBER PLATE LIGHT RH	Serviceable	75.00 FL	*- FL
10	1		*BACK DOOR NISSAN LOGO EMBLEM	Necessary	85.00 FL	*85.00 FL
11	1		*BACK DOOR LOCK ASSY	Serviceable	320.00 FL	*- FL
12	1		*TAIL LAMP ASSY LH	Serviceable	280.00 FL	*- FL
13	1		*TAIL LAMP ASSY RH	Serviceable	280.00 FL	*- FL
14	1		*REAR BUMPER ASSY	Deformed	650.00 FL	*650.00 FL
15	1		*REAR BUMPER RETAINER LH	Necessary	38.00 FL	*38.00 FL
16	1		*REAR BUMPER RETAINER RH	Serviceable	38.00 FL	*- FL
17	1		*REAR BUMPER REFLECTOR ASSY LH	Serviceable	65.00 FL	*- FL
18	1		*REAR BUMPER REFLECTOR ASSY RH	Serviceable	65.00 FL	*- FL
19	1		*REAR REINFORCEMENT BAR	Serviceable	240.00 FL	*- FL
20	1		*REAR END PANEL OUTER	Bent	280.00 FL	*280.00 FL
21	1		*REAR END PANEL INNER	Repair	760.00 FL	*- FL
22	1		*REAR FLOOR PANEL ASSY (NPA)	Repair	0.00 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING LH	Not Necessary	150.00 FS	*- FS
24	1		*REAR WINDSCREEN MOULDING RH	Not Necessary	120.00 FS	*- FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
26	1		*70KM/HR STICKER	Necessary	30.00 FS	*10.00 FS
27	1		*8PAX STICKER	Not Necessary	20.00 FS	*- FS
28	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
29	1		*REVERSE PARKING SENSOR	Cut	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,841.00</b>	<b>2,563.00</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	1,806.30	675.90
<b>Total Parts (\$\$)</b>	<b>5,034.70</b>	<b>1,887.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR DISMANTLE,PANEL BEATING,RESHAPE AND REPLACEMENT TAILGATE ASSY,REAR END PANEL,REAR BUMPER AND ALL AFFECTED AREAS	New	1,000.00	700.00
2	LABOUR FOR SPRAY PAINT TAILGATE,END PANEL AND ALL AFFECTED AREAS	New	800.00	600.00
3	LABOUR FOR REPLACE AND DISTANCE TESTING REVERSE SENSOR	New	80.00	60.00
4	LABOUR FOR REMOVE AND REPLACE REAR WINDSCREEN AND CONDUCT WATER LEAKING TEST	New	180.00	30.00
5	LABOUR FOR PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,140.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >