



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2006655
INV Date 25/09/2020
Reference CC6/EQI20008942/Kga3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SMN 9822H
Insured Veh. SGW 1809Z
Claim No. DM20HO01230-JG
Policy No.
Accident Date 21/08/2020
Inspection Date 25/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI20008942/Kga3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 25-09-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGW 1809Z	Veh. Inspected	SMN 9822H
Policy No.		Coverage (\$)	0.00
Claim No.	DM20HO01230-JG	Excess (\$)	0.00
Assign From		Assign Date	25/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZVW400032391	Colour	WHITE
Odometer	106712	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FIREMAX	9 mm
L/H Front Tyre	215/60 R16	FIREMAX	9 mm
R/H Rear Tyre	215/60 R16	BRIDGESTONE	2 mm
L/H Rear Tyre	215/60 R16	BRIDGESTONE	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/08/2020	Inspection Date	25/08/2020
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 9822H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	1,110.60	1,110.60
1	REAR PRIUSCX EMBLEM	NECESSARY	52.10	52.10
1	REAR TOYOTA EMBLEM	NECESSARY	63.40	63.40
1	REAR HYBRID EMBLEM	NECESSARY	46.65	46.65
1	TAIL LAMP LH	SERVICEABLE	667.70	-
1	TAIL LAMP RH	MTG CRACKED	667.70	580.00
1	REAR BUMPER	BUCKLED	556.40	523.00
1	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	END PANEL	TO REPAIR SEE LABOUR	696.30	-
1	END PANEL TOP COVER	SERVICEABLE	181.60	-
1	END PANEL TOP COVER CLIPS	NOT NECESSARY	30.00	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,030.61	-606.44
			3,091.84	1,819.31
<u>SPECIAL NETT ITEMS</u>				
1	REAR LICENSE PLATE WITH HOLDER (SN)	SERVICEABLE	45.00	-
1	REVERSE SENSOR (SN)	DENTED	240.00	200.00
			285.00	200.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, CHISEL, DISMANTLE ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF END PANEL, REAR FENDER LH AND REAR FENDER RH.		1,200.00	500.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.		900.00	600.00
	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		60.00	20.00

Report Ref No. CC6/EQI20008942/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR.TO EFFECT REPLACE OF REAR BUMPER. TO TUFF KOTE & UNDERSEAL MATERIALS.		80.00	50.00
			100.00	30.00
			2,340.00	1,200.00
GRAND TOTAL			5,716.84	3,219.31
RECOMMENDED COST OF REPAIRS				3,219.31

Report Ref No. CC6/EQI20008942/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 982ZH

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

