

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

## Lonpac Insurance Bhd

300 Beach Road 07 The Concourse  
#17-04

Singapore (199555)

ATTN: MOTOR CLAIM DEPARTMENT

DEAR SIR / MADAM :

**ACCIDENT REPAIR ON: SLW1525H**

MODEL : BMW 316i AT

POLICY NO : 5107403266-01

CHASSIS NO : WBA3A16080NS36130

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Authen  
Repairer After Paint  
2 days*

Date: 25/8/2020

Page : 1 of 2

DATE / TIME OF ACCIDENT: 15/08/2020 Time: 1215Hrs at CTE after PIE.  
THIRD PARTY VEHICLE NO: GBC5083M

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price S\$	Condition	Amount S\$
S/N					
1	Rear bumper	1	1,178.00		1,178.00 X
Sub-Total:					1,178.00
Total Parts :					1,178.00

### Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00	200
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	400
3	Provide skill labour to disconnect and check electrical wiring	80.00	X
5	Provide skill labour to remove and replace bumper sensors	100.00	X
6	Provide skill labour to check and re-adjust wheel alignment	80.00	X
Total Labour:		2,960.00	
Total Parts & Labour:		4,138.00	
GST 7%		289.66	
Grand Total:		4,427.66	

Estimate Repair Duration 03 days

ACCIDENT VEHICLE OF : SLW1525H

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,