



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2006001  
INV Date 02/09/2020  
Reference CS/AGI20008946/Uqf3n2  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. XD 2962E  
Insured Veh. SMS 9192R  
Claim No. C10007064  
Policy No.  
Accident Date 18/08/2020  
Inspection Date 26/08/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

**LKK Auto Consultants Pte Ltd**

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20008946/Uqf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 02-09-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMS 9192R	<b>Veh. Inspected</b>	XD 2962E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10007064	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	25/08/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	ISUZU CYZ52L (M)	<b>c.c</b>	15681
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	JALCYZ52L87000066	<b>Colour</b>	WHITE
<b>Odometer</b>	836286	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	295/80 R22.5	KPATOS	5 mm
<b>L/H Front Tyre</b>	295/80 R22.5	KPATOS	5 mm
<b>R/H Rear Tyre</b>	295/80 R22.5 (D/D)	ECOSTAR	5/5 5/5 mm
<b>L/H Rear Tyre</b>	295/80 R22.5 (D/D)	ECOSTAR	5/5 5/5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	18/08/2020	<b>Inspection Date</b>	26/08/2020
<b>Survey held at</b>	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2962E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT CORNER PANEL-LH (CRACKED)	NOT CONSISTENT WITH THE IMPACT	566.80	-
1	FRONT CORNER PANEL RUBBER SEAL-LH	NOT NECESSARY	88.40	-
1	FRONT BUMPER	DENTED	1,597.70	1,597.70
1	FRONT BUMPER BRACKET-LH	NOT NECESSARY	221.00	-
1	FRONT BUMPER TOP STEP GARNISH-LH	DEFORMED	110.50	110.50
1	FRONT BUMPER TOP CENTER STEP GARNISH-LH	NOT NECESSARY	201.50	-
1	HEADLAMP ASSY-LH	CRACKED	434.20	434.20
1	HEADLAMP BRACKET-LH	NOT NECESSARY	354.90	-
1	HEADLAMP RIM-LH	BROKEN	127.40	127.40
2	FRONT BUMPER SIGNAL LAMP-LH/RH @\$208.00	N/S CRACKED	416.00	208.00
2	FRONT BUMPER FOG LAMP-LH/RH @\$551.20	N/S CRACKED	1,102.40	551.20
1	FRONT BUMPER SIDE BRACKET-LH	NOT NECESSARY	227.50	-
1	FRONT BUMPER LAMP BRACKET-LH	NOT NECESSARY	175.50	-
1	STAND PANEL-LH	NOT NECESSARY	694.00	-
1	STAND PANEL ALLOY MAT-LH	NOT NECESSARY	286.00	-
1	STEP GARNISH-LH	GRAZED	494.00	494.00
1	STEP GARNISH COVER-LH	NOT NECESSARY	494.00	-
1	STEP GARNISH ALLOY MAT-LH	NOT NECESSARY	386.00	-
1	STEP ALLOY BRACKET-LH	NOT NECESSARY	839.00	-
1	FRONT FENDER SIGNAL LAMP-LH	CRACKED	134.00	134.00
1	FRONT FENDER PANEL-LH	TO REPAIR SEE LABOUR	563.00	-
	LESS 10% DISCOUNT		-951.38	-
	LESS 15% DISCOUNT		-	-548.55
			8,562.42	3,108.45
	<b><u>LABOUR</u></b>			
	LABOUR TO REFOCUS & CONNECT ALL LAMP & WIRING.		380.00	20.00
	LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER PANEL-LH.		1,500.00	480.00
	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA.		1,200.00	400.00

Report Ref No. CS/AGI20008946/Uqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOFING AT AFFECTED AREA.	NOT NECESSARY	580.00	-
			3,660.00	900.00
GRAND TOTAL			12,222.42	4,008.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/AGI20008946/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. XD 2962E

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. XD 2962E

### RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 2962E

RE-INSPECTION

