

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III20008947/UGS3Q2**Date:** 12/11/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLL5333B	<b>Insured Vehicle No :</b>	SHA7924M
Date of Loss: 24/08/2020	Nature of Claim: TP	Claim No: MCT20080367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLL5333B</b>		
Make & Model:	HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	L15B4036178
Reg. Date:	24/05/2016 (Man. Year: 2016)	Chassis No:	RU11116172
Colour:	White	Odometer:	74226 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	53,912.51	17,451.20	36,461.31	67.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	3,860.00	6,600.00	63.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>64,372.51</b>	<b>21,311.20</b>	<b>43,061.31</b>	<b>66.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>17,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>64,372.51</b>	<b>17,000.00</b>	<b>47,372.51</b>	<b>73.59</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
	<b>Nett Liability (S\$)</b>	<b>17,700.00</b>		

INSPECTION

Date of Assignment:	25/08/2020	
Date Inspected:	25/08/2020	Inspected At: Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	10.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2020)
<b>Parts:</b> 144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLL5333B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	915.00 F	*855.20 FL
2	2		*BONNET HINGES	Bent	170.00 F	*170.00 FL
3	1		*BONNET INSULATOR	Deformed	211.30 F	*211.30 FL
4	1		*SET BONNET INSULATOR CLIPS	Necessary	35.00 F	*35.00 FL
5	1		*BONNET LOCK	Twisted	135.50 F	*135.50 FL
6	2		*BONNET RUBBERS	Necessary	64.00 F	*64.00 FL
7	1		*FRONT BUMPER	Torn	950.00 F	*752.50 FL
8	1		*FRONT BUMPER REINFORCEMENT	Distorted	480.00 F	*321.00 FL
9	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
10	2		*FRONT BUMPER BRACKETS	No such part	230.00 F	*- FL
11	1		*FRONT BUMPER CENTRE GRILLE	Torn	285.00 F	*162.30 FL
12	1		*FRONT BUMPER LOWER SPOILER	Deformed / Torn	525.00 F	*480.00 FL
13	1		*FRONT BUMPER UNDER COVER	Not Necessary	480.00 F	*- FL
14	1		*SET FRONT BUMPER UNDER COVER CLIPS	Not Necessary	35.00 F	*- FL
15	1		*FRONT BUMPER TOW COVER	Not Necessary	45.00 F	*- FL
16	2		*FRONT BUMPER FOG LAMP COVERS	Twisted / Torn	360.00 F	*242.00 FL
17	2		*FRONT BUMPER FOG LAMPS	Cracked	890.00 F	*654.00 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
19	1		*FRONT GRILLE	Broken	525.00 F	*525.00 FL
20	1		*FRONT GRILLE OUTER GARNISH	Cracked	548.00 F	*385.00 FL
21	1		*FRONT GRILLE H LOGO	Necessary	38.80 F	*38.80 FL
22	2		*HEADLAMPS	Cracked	4,500.00 F	*3,718.20 FL
23	1		*HEADLAMP LOWER BRACKETS	N/s Cracked	170.00 F	*85.00 FL
24	1		*FRONT SUPPORT PANEL	Bent	745.11 F	*576.20 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	322.30 F	*188.20 FL
26	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 F	*50.00 FL
27	2		*FRONT FENDERS	Repair	1,376.00 F	*- FL
28	2		*FRONT FENDER INNERSHIELDS	Not Necessary	333.00 F	*- FL
29	2		*FRONT FENDER OUTER PROTECTORS	Deformed / Torn	590.00 F	*590.00 FL
30	1		*AIR CON CONDENSER	Bent / Punctured	1,568.00 F	*1,005.50 FL
31	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	296.00 F	*- FL
32	1		*RADIATOR	Bent / Punctured	1,817.50 F	*1,649.40 FL
33	1		*RADIATOR FAN COWLING	Cracked	288.30 F	*245.30 FL
34	1		*RADIATOR FAN MOTOR	Jammed	488.20 F	*385.00 FL
35	1		*RADIATOR FAN BLADE	Serviceable	101.50 F	*- FL
36	1		*FRONT FENDER INNER PANEL N/S	Repair	525.30 F	*- FL
37	1		*FRONT WHEEL HOUSING PANEL N/S	Repair	988.20 F	*- FL
38	1		*FRONT LOCK CENTRE BRACKET	Cracked	115.00 F	*115.00 FL
39	1		*AIR DUCT	Twisted	215.00 F	*215.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIR CLEANER BOX	Not Necessary	788.00 F	*- FL
41	1		*FRONT WHEEL PANEL GARNISH	Not Necessary	344.20 F	*- FL
42	1		*RESONATOR BOX	Not Necessary	385.20 F	*- FL
43	2		*FRONT GRILLE CHROME MOULDING	Scratched	197.00 F	*197.00 FL
44	1		*BATTERY TRAY	Not Necessary	180.20 F	*- FL
45	1		*WASHER TANK	Not Necessary	305.20 F	*- FL
46	1		*FRONT WINDSCREEN	Not Necessary	1,488.20 F	*- FL
47	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
48	1		*TAILGATE H LOGO	Necessary	35.80 F	*35.80 FL
49	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
50	1		*TAILGATE OUTER HANDLE GARNISH	Cracked	399.20 F	*399.20 FL
51	1		*TAILGATE REFLECTORS	N/s Cracked	921.00 F	*280.50 FL
52	1		*TAILGATE INNER LOCK	Twisted	198.50 F	*198.50 FL
53	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	321.70 F	*321.70 FL
54	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	45.00 F	*- FL
55	2		*TAILGATE DANPERS	Not Necessary	598.20 F	*- FL
56	1		*TAILGATE WEATHERSTRIP	Twisted	135.70 F	*135.70 FL
57	1		*TAILGATE REAR WIPER ARM	Not Necessary	188.20 F	*- FL
58	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	695.00 F	*- FL
59	1		*TAILGATE KEYLESS SENSOR	Cracked	180.00 F	*180.00 FL
60	1		*REAR WINDSCREEN	Not Necessary	1,566.20 F	*- FL
61	1		*REAR WINDSCREEN MOULDING	Necessary	181.00 F	*181.00 FL
62	1		*TAILGATE TOP SPOILER	Not Necessary	950.00 F	*- FL
63	1		*REAR BUMPER	Dented	762.70 F	*762.70 FL
64	2		*REAR BUMPER SIDES	Repair	570.20 F	*- FL
65	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.40 F	*- FL
66	2		*REAR BUMPER REFLECTORS	Cracked	170.00 F	*170.00 FL
67	1		*REAR BUMPER DIFFUSER	Twisted	348.20 F	*348.20 FL
68	1		*SET REAR BUMPER DIFFUSER CLIPS	Necessary	50.00 F	*50.00 FL
69	2		*REAR BUMPER MUDFLAPS	Not Necessary	290.00 F	*- FL
70	2		*TAILLAMPS	Cracked	970.40 F	*970.40 FL
71	2		*TAILGATE HOUSING PANELS	Repair	390.00 F	*- FL
72	1		*REAR END PANEL	Badly Dented	514.00 F	*514.00 FL
73	1		*REAR END PANEL TOP GARNISH	Twisted	184.00 F	*184.00 FL
74	1		*REAR FLOOR PANEL	Repair	912.00 F	*- FL
75	1		*REAR FLOOR PANEL TOP BOARD	Torn	499.20 F	*499.20 FL
76	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	685.00 F	*685.00 FL
77	1		*REAR FLOOR PANEL SIDE PANEL N/S	Repair	399.20 F	*- FL
78	1		*REAR FLOOR PANEL SIDE TOP PANEL N/S	Repair	299.20 F	*- FL
79	2		*REAR FENDERS	Repair	1,770.20 F	*- FL
80	2		*REAR FENDER OUTER PROTECTORS	Torn	528.00 F	*430.00 FL
81	2		*REAR FENDER INNER TRIM BOARD	Serviceable	1,290.60 F	*- FL
82	1		*REAR EXHAUST	Not Necessary	899.20 F	*- FL
83	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
84	2		*REAR SHOCK ABSORBERS	Not Necessary	610.00 F	*- FL
85	2		*REAR WHEELHUB BEARINGS	Not Necessary	900.00 F	*- FL
86	1		*REAR AXLE ARM	Not Necessary	1,885.00 F	*- FL
87	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	199.00 F	*- FL
88	1		*REAR WHEEL HOUSING PANELS N/S	Repair	1,150.00 F	*- FL
89	1		*REAR END LOCK SENSOR	Not Necessary	288.50 F	*- FL
90	1		*REAR FENDER UNDER TRIM N/S	Not Necessary	299.30 F	*- FL
91	1		*REAR CHASSIS MEMBER N/S	Not Necessary	699.20 F	*- FL
92	2		*REAR DOOR	Not Necessary	1,996.40 F	*- FL
93	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
94	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	250.00 FS	*- FS
95	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
96	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
97	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
98	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
99	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
100	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
101	1		*BATTERY	Not Necessary	220.00 FS	*- FS
102	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>53,912.51</b>	<b>21,766.50</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	4,315.30
<b>Total Parts (\$\$)</b>	<b>53,912.51</b>	<b>17,451.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING.	New	100.00	30.00
2	TO DISMANTLE & REFIX REVERSE CAMERA.	New	100.00	50.00
3	TO TRANSFER TAILGATE MECHANISM.	New	100.00	60.00
4	TO DISMANTLE & REPLACING REAR WINDSCREEN.	New	150.00	120.00
5	TO DISMANTLE & REFIX REAR EXHAUST.	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	New	150.00	80.00
7	TO DISMANTLE & REFIX PETROL TANK.	New	100.00	0.00
8	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	New	380.00	0.00
9	TO SPRAY RUST PROOFING.	New	200.00	120.00
10	TO REFILL AIR CON GAS.	New	150.00	100.00
11	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
12	TO CONDUCT WHEEL ALIGNMENT.	New	100.00	0.00
13	TO DISMANTLE & REFIX FRONT WINDSCREEN.	New	150.00	0.00
14	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	New	4,500.00	1,500.00
15	TO PUTTY & SPRAY PAINTING.	New	3,800.00	1,800.00
			<b>Gross Labour Cost (\$\$)</b>	<b>10,460.00</b>
				<b>3,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >