Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## **VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CS/MSG20008951/UQF3E2

Date: 07/09/2020

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29141713 Claimant Vehicle SLA5232S

Insured Vehicle No: SLQ450C No:

Date of Loss: 22/08/2020 Nature of Claim: TP Claim No: 627659

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLA5232S** 

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4027203 Reg. Date: 02/03/2016 (Man. Year: 2015) Chassis No: RU11107202 Colour: Odometer: 63354 km Black

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

215/60 R16 Front Tyre Size: 215/60 R16 Rear Tyre Size: Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Rear Right Side: Front Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,902.80	3,464.64	3,438.16	49.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,940.00	800.00	29.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,642.80	5,404.64	4,238.16	43.95
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	9,642.80	4.300.00	5.342.80	55.41

**INSPECTION** 

Date of Assignment: 25/08/2020

Date Inspected: 25/08/2020 Inspected At: Quan De Motor Trading

BLK 1 KAKI BUKIT AVENUE 6 #01-67

**AUTOBAY SINGAPORE 417883** 

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## **REPAIR DETAILS**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2020)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA5232S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 FL	*121.30 FL
2	1		*TAILGATE	Badly Dented	953.00 FL	*953.00 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
4	1		*TAILGATE INNER LOCK	Twisted / Jammed	198.50 FL	*198.50 FL
5	1		*TAILGATE INNER TRIM BOARD	Deformed / Twisted	321.70 FL	*321.70 FL
6	1		*TAILGATE WEATHERSTRIP	Serviceable	148.50 FL	*- FL
7	1		*REAR BUMPER	Dented / Deformed	566.20 FL	*566.20 FL
8	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	71.00 FL	*- FL
9	1		*REAR BUMPER SIDE	Deformed / Twisted	235.10 FL	*235.10 FL
10	1		*REAR BUMPER LOWER DIFFUSER	Twisted	348.20 FL	*348.20 FL
11	1		*REAR END PANEL	Badly Dented	514.00 FL	*514.00 FL
12	1		*REAR END PANEL TOP GARNISH	Twisted	166.80 FL	*166.80 FL
13	2		*TAILLAMPS	Not Necessary	901.00 FL	*- FL
14	1		*REAR FLOOR PANEL	Repair	912.30 FL	*- FL
15	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	388.20 FL	*- FL
16	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	522.30 FL	*522.30 FL
17	1		*REAR FENDER OUTER PROTECTOR	O/S Torn	430.00 FL	*215.00 FL
18	1		*REAR EXHAUST	Repair	899.20 FL	*- FL
19	1		*SET REAR BUMPER REVERSE SENSOR	Not fitted	300.00 FS	*-FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
21	1		*REAR SPOILER	Not fitted	300.00 FS	*-FS
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
	Sub Total (S\$)			8,453.50	4,308.30	
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,550.70	843.66	
				T. (.) D. (.) (0.0)	0.000.00	0.404.04
				Total Parts (S\$)	6,902.80	3,464.64

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO CHECK WIRING	New	50.00	30.00				
2	TO REMOVE & REFIX REVERSE CAMERA	New	120.00	50.00				
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00				
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	120.00	80.00				
5	TO SPRAY RUST PROOFING	New	100.00	60.00				
6	LABOUR FOR PANEL BEATING, WELDING & RENEW PARTS	New	1,000.00	800.00				
7	SPRAY PAINTING	New	1,200.00	800.00				
	Gross Labour Cost (S\$)		2,740.00	1,940.00				
	Report was unsubmitted during	this print-out.						

< END OF ESTIMATES >