

(08/11/13) Wef

ASS. REC. BY: Merica

REF:

MSG
CS/ ~~ET~~ 20008951/Uqf3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLA 52325
at Workshop m/s Quang Ao
of _____
Insured: SLQ 450C
Policy No. 29141713
Claims No. 627659
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

250 A

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLA 52325 Yr Regn: 3.16
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA /
Make: Honda Vezel C.C. 1496
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 63354 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: Ru11107202
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 2.5/60 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 22/8/20 D.O.I. 25/8/20
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/9/20 No remote center
4/5 @ 4300 confirmed with Jennifer (Red \$5342.80, 55%)

03/09/20@1pm revised to Chhia Nyuk Pui via Merimen.

Date/Time, File Pass to?

☐

: Preli. Report

1) 03/09 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

_____ S + RS, _____ SI

Photos

Others

TOTAL

Report Format : MER-TP

Lump Sum 4300 (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
 AUTOBAY, SINGAPORE 417883
 HP: 96709191 FAX: 66840767

not Attached
 LR
 1/5th 4300
 5 days

MSIG Insurance (S) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807
 Attn: Motor Claims Department

Attn: Mr. Marcus Chua
 (Surveyor)

Date: 25 August 2020

**Accident on 22/08/2020 Involving vehicles SLA52325 & 5LQ450C
 along Jurong East Avenue 1**

Estimate cost of repair to vehicle SLA52325 Honda Vezel 1.5A

1 pc.	rear windscreen moulding	RPC	\$ 121.30	/
1 pc.	tailgate	Body	\$ 953.00	/
1 pc.	tailgate 'VEZEL' emblem	NR	\$ 56.20	/
1 pc.	tailgate inner lock	Twl/Tm	\$ 198.50	/
1 pc.	tailgate inner trim board	De/Tm	\$ 321.70	/
1 pc.	tailgate weatherstrip	SVL	\$ 148.50	X
1 pc.	rear bumper	Do/De	\$ 566.20	/
2 pcs.	rear bumper side retainers @ \$35.50	11	\$ 71.00	X
1 pc.	rear bumper side	De/Tm	\$ 235.10	/
1 pc.	rear bumper lower diffuser	Twl	\$ 348.20	/
1 pc.	rear end panel	Body	\$ 514.00	/
1 pc.	rear end panel top garnish	Twl	\$ 166.80	/
2 pcs.	taillamps @ \$450.50	11	\$ 901.00	X
1 pc.	rear floor panel	R	\$ 912.30	X
1 pc.	rear floor panel top board	11	\$ 388.20	X
1 pc.	rear floor panel tools sponge	Twl	\$ 522.30	/
2 pcs.	rear fender outer protector @ \$215.00	0/5/2011	\$ 430.00	IPC
1 pc.	rear exhaust	R	\$ 899.20	X
			\$ 7,753.50	
Less 20%			\$ 1,550.70	
			\$ 6,202.80	

S.Nett Items:

1 set	rear bumper reverse sensor	NF	\$ 300.00	X
1 pc.	rear windscreen sealant	NR	\$ 50.00	40
1 pc.	rear spoiler	NF	\$ 300.00	X
1 set	rear bumper clips	NR	\$ 50.00	✓

Sub-total: \$ 6,902.80

1-4218.30
 252
 3374.64

Labour Charges:

To check wiring
 To remove & refix reverse : *camera*
 To remove & refix rear windscreen
 To remove & refix interior upholstery
 To spray rust proofing
 Labour for panel beating, welding & renew parts
 Spray painting

Bal c/f \$ 6,902.80

\$ 50.00 *30*
 \$ 120.00 *50*
 \$ 150.00 *120*
 \$ 120.00 *80*
 \$ 100.00 *60*
 \$ 1,000.00 *800*
 \$ 1,200.00 *800*

Total: \$ 9,642.80

560464
4323

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: