### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Irene Tay Hui Ping Date: 27 Aug 2020

## **Preliminary Advice**

Insured Vehicle No : YN6677M

TP Vehicle No : SJM6666C : 21/08/2020 Accident Date Make : TOYOTA HIACE Assignment Date : 25/08/2020

Date of Inspection : 26/08/2020 Est. Duration of Repair

Inspection At : JIN AUTO SERVICES PTE LTD (DEFU)

BLK 14 DEFU LANE 10, #01-410/412

SINGAPORE 539195

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,919.23
Revised Amount	:S\$	4,069.23
Check Items (Estimated)	:S\$	360.00
Total	:S\$	4,429.23

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

#### Remarks

	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
,	)	Other comments :