

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6817D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER-RR BUMPER	DEFORMED	459.40	459.40
1	MOULDING ASSY-RR BUMPER C	CRACKED	451.25	451.25
10	HYUNDAI BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	CAP-RR HOOK	CUT	98.80	98.80
1	REFLECTOR/REFLEX ASSY-RR	CRACKED	31.90	31.90
1	COVER-RR BPR UNDER CTR	TO REPAIR SEE LABOUR	155.00	-
1	BRACKET ASSY-RR BUMPER SI	DEFORMED	55.80	55.80
1	UNIT ASSY-BSD LH (BLINDSPORT)	CRACKED	1,487.00	1,487.00
	LESS 20% DISCOUNT		-552.23	-516.83
			2,208.92	2,067.32
	SPECIAL NETT ITEMS			
1	PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	RENEW ADVERTISEMENT STICKER (SN)	NECESSARY	100.00	100.00
			150.00	150.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER-RR BPR UNDER CTR.		400.00	320.00
	SPRAYPAINT CHARGE.		300.00	200.00
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
	TO DIAGNOSETICE AND RE-SET.		150.00	120.00
			980.00	700.00
	GRAND TOTAL		3,338.92	2,917.32
	RECOMMENDED COST OF REPAIRS			2.917.32

RECOMMENDED COST OF REPAIRS		2,917.32
(CONFIRMED)		

Report Ref No. NS/INC20008955/T1tf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser