

ASS. REC. BY:

REF:

NS/INC20008957/T1vf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

SMN 5878Z

Policy No. _____

5112624286

Claims No. _____

MT/1101115-003

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHA 5789A

Yr Regn: _____

2014 Yr 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Hyundai 140

c.c.

1685

Colour: _____

Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

73553

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KMHLK4144 E4053751

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

205/60R16

Waste

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Waste

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. 21/8/20

D.O.I. 24/8/20

Survey held at

Conf. Tel. for Logg.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S, Rear O/S, U/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

To check repair work, inform Conf. Tel. for book value

17/9/20 COR LS \$11,900 (Red 22,545.32, 65%)

BV: \$21,161.01 NV:19,735 NV:\$1426.01

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 17/9/20-Typist

Report Format: TP

Lump Sum / LB. H. C. LS \$11,900

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Updated 11 Feb 2020

DATE: 24.08.2020

MODEL: HYUNDAI I40

VEHICLE NO.: SHA5789A

INSURANCE: NTUC

MVA: LKK-TAUFIKH

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Bonnet	1		\$2,265.90 <i>Rp</i>
	Bonnet Hinge (RH)	1		\$41.00 <i>Rp</i>
	Bonnet Lock	1		\$42.40 <i>x</i>
	Radiator Grille H Emblem	1		\$39.50 <i>x</i>
	Radiator Grille	1		\$1,480.00 <i>dep-?</i>
	Front Bumper Cover	1		\$1,052.20 <i>eng</i>
	Front Bumper Sponge	1		\$99.20 <i>eng</i>
	Front Bumper Reinforcement	1		\$438.40 <i>?</i>
	Front Bumper Grille (RH)	1		\$93.60 <i>de</i>
	Front Bumper Centre Grille	1		\$114.00 <i>de</i>
	Front Bumper Lip	1		\$54.00 <i>mis</i>
	Front Bumper Bracket Top (RH)	1		\$22.40 <i>eng</i>
	Front Bumper Centre Grille Top Garnish	1		\$80.00 <i>x</i>
	Front Bumper Side Cover (RH)	1		\$25.40 <i>?</i>
	Front Bumper Bracket (RH)	1		\$24.60 <i>eng</i>
	Front Bumper Side Bracket (RH)	1		\$14.30 <i>?</i>
	Front Bumper Grille Air Duct (RH)	1		\$26.20 <i>?</i>
	Headlamp Support Panel Assy	1		\$907.40 <i>?</i>
	Headlamp (RH)	1		\$1,388.00 <i>eng</i>
	Headlamp Support Top Cover	1		\$222.60 <i>x</i>
	Front Fender (RH)	1		\$663.00 <i>bt</i>
	Front Fender Shield (RH)	1		\$174.90 <i>fn</i>
	Rocker Panel Outer Garnish (RH)	1		\$403.00 <i>Rp</i>
	Wiper Container	1		\$61.90 <i>?</i>
	Wiper Container Motor	1		\$75.00 <i>?</i>
	Front Wheel Rim (RH)	1		\$650.60 <i>bt</i>
	Front Wheel Hub Cap (RH)	1		\$107.10 <i>de</i>
	Front Wheel Bearing	1		\$540.50 <i>?</i>
	Front Wheel Hub Assy	1		\$153.60 <i>?</i>
	Front Shock Absorber Assy (RH)	1		\$342.20 <i>?</i>
	Front Shock Absorber Mounting (RH)	1		\$217.60 <i>?</i>
	Front Shock Absorber Fork (RH)	1		\$212.15 <i>?</i>
	Front Suspension Upper Arm (RH)	1		\$250.40 <i>?</i>
	STG Tie Rod End (RH)	1		\$135.00 <i>?</i>
	Front Suspension Lower Arm (RH)	1		\$595.90 <i>?</i>
	Knuckle Arm (RH)	1		\$1,104.00 <i>?</i>
	Rear Bumper	1		\$1,106.00 <i>de</i>
	Rear Bumper Reinforcement Bracket (RH)	1		\$80.30 <i>x</i>
	Rear Bumper Reinforcement	1		\$428.40 <i>x</i>
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 <i>eng</i>
	Rear Bumper Bracket (RH)	1		\$35.60 <i>eng</i>
	Rear Bumper Sponge	1		\$119.50 <i>?</i>

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper Under Cover	1		\$228.00 ?
	Tail Lamp (RH)	1		\$697.80 <i>on</i>
	Spare Tyre Panel	1		\$852.80 <i>bt RY</i>
	Tail Lamp Quarter Panel (RH)	1		\$226.50 <i>RY</i>
	Tail Lamp Panel Top (RH)	1		\$545.90 ?
	Tail Lamp Lower Panel (RH)	1		\$225.60 ?
	Rear Towing Hook	1		\$94.60 X
	Member-Assy-Rear Floor Centre	1		\$570.40 <i>RY</i>
	Rear Panel Inner Panel (RH)	1		\$380.00 <i>RY</i>
	Exhaust Pipe Insulator (RH)	1		\$58.55 <i>bt</i>
	Exhaust Silencer (RH)	1		\$967.70 <i>RY</i>
	Exhaust Pipe Hanger (RH)	1		\$58.55 X
	Exhaust Pipe Centre	1		\$730.10 X
	Rear Fender (RH)	1		\$2,171.40 <i>bt</i>
	Rear Fender With Housing (RH)	1		\$4,736.80 <i>RY</i>
	Rear Fender Inner Panel (RH)	1		\$1,310.60 <i>RY</i>
	Rear Fender Air Duct (RH)	1		\$51.60 <i>mis</i>
	Rear Windscreen Moulding	1		\$51.80 <i>net</i>
	Rear Tyre Rim (RH)	1		\$325.30 <i>bt</i>
	Rear Tyre Wheel Cap (RH)	1		\$107.10 <i>del</i>
	Rear Wheel Hub with Bearing (RH)	1		\$362.00 ?
	Rear Trailing Arm (RH)	1		\$192.00 ?
	Rear Assist (RH)	1		\$145.70 ?
	Rear Shock Absorber (RH)	1		\$276.30 ?
	Rear Shock Absorber Mounting (RH)	1		\$81.30 ?
	Rear Upper Arm (RH)	1		\$335.75 ?
	Rear Lower Arm (RH)	1		\$353.80 ?
	Rear Knuckle Arm (RH)	1		\$545.60 ?
	Rear Cross Member	1		\$1,021.50 X
	Rear Stabilizer Bar	1		\$399.20 X
	Rear Stabilizer Link (RH)	1		\$85.90 ?
	SUB TOTAL			\$34,099.90
	LESS 20%			\$6,819.98
	DISCOUNTED TOTAL			\$27,279.92
	Rear Windscreen Sealant	1		\$46.00 <i>net</i>
	Rear Door APPS Sticker (RH)	1		\$80.00 X
	SUB TOTAL			\$126.00
	LESS 10%			\$12.60
	DISCOUNTED TOTAL			\$113.40
	Frnt Tyre (RH)	1		80% \$216.00 <i>particul</i>
	Rear Tyre (RH)	1		80% \$216.00 <i>particul</i>
	NETT SUB TOTAL			\$432.00
	SPARE PARTS DISCOUNTED TOTAL			\$27,825.32

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Labour Charge			
	Panel Beating			\$2,400.00 1680
	Spray Painting Charge			\$2,000.00 1400
	Wiring Charge			\$100.00 50
	Tuff Kote			\$200.00 200
	Towing Charge - KING DOLLY			\$60.00 X
	Front Chassis Alignment Charge			\$400.00 250? plus h.
	Remove/Refix Cushion & Upholstery Rear			\$150.00 60
	Remove/Refix Rear Windscreen Glass			\$120.00 1 ✓
	Remove/Refix Reverse Sensor			\$120.00 30
	Remove/Refix Undercarriage (RR)			\$400.00 150? plus h.
	Remove/Refix Exhaust Pipe			\$150.00 80
	Remove/Refix Undercarriage (Frt)			\$400.00 150? plus h.
	Four Wheel Alignment			\$120.00 80
	TOTAL LABOUR			\$6,620.00
	ESTIMATE TOTAL			\$34,445.32
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

P3/B

Tanphir 97493749
 'WP' 24/8/2019 4pm
 Lampsun 10 days
 * - To check repair limit
 * - please provide book value.
 Tanphir@kkaant.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 8280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508869

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Telok Ayer Street Singapore 06649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

801 Yishun Industrial Park A Singapore 768732

Date/Time: 22.08.2020 11:39

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305418178

OWNER

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

QUANTITY CARD NO.

REGN NO:

SHA5789A

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

21.08.2020 23:30

YR OF MANU.

30.04.2014

TARGET DATE

CHASSIS CODE

KMHLB41UMEU053751

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 21.08.2020

NATURE: 3P 21.08.2020/C

S/NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Check-in Slip

Exit Pass

No.: SHA5789A

LIMITS

Vehicle No.:

SHA5789A

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE


Job Requisition

1. Date: <u>22/08/2020</u> Time Received: <u>0100/0102</u>		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input type="checkbox"/> Normal Tow <input checked="" type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>Mr. Lim</u> Contact No. : <u>96971515</u> Vehicle No. : <u>SHA5789A</u> Make / Model / Colour : <u>i-40</u> Email :		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input checked="" type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks: <u>front / Rear Tyre puncture</u> <u>use Kdolly?</u>
7. Location: <u>51 Sims Dr</u>		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____			

10. Odometer Reading : _____

Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E

11. Radio / CD Player
☐ OK
☐ Faulty
☐ Not tested



: Cracked X : Dented
/ : Scatched O : Missing

Signature of Customer

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☒ GAO ☐ TZ ☐ YISHUN ☐ OTHERS TOWING

Name of Driver : Hee

Vehicle No. : YM 9148J

Time Dispatch : 0102

Time of Arrival : 0140

Time Completed : 0225

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

22/08/2020

Date

0225

Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2020 11:03
Date Of Accident	21/08/2020 23:30
Exact Location Of Accident	KPE TWDS CITY AFTER AIRPORT RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA5789A
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	LIM LYE SOON
NRIC No	SXXXX755E
Date Of Birth	01/06/1952
Occupation	OUTDOOR
Date Of Driving Pass	10/08/1972
Driving Experience	48 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96971515
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	826 12-434 JURONG WEST STREET 81
Postcode	640826
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN5878Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM HANRONG CALVIN
NRIC/Passport Number	SXXXX373Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT LEFT
No. Of Passenger (Including Driver)	


DETAILS OF INJURED PERSON 1

Name	LIM LYE SOON
------	--------------

Approximate Age	68
Injuries Sustain	NECK,BACK,ARMS
Injured person in which vehicle?	SHA5789A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

KPE \rightarrow City



→ Stetant detached D

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: Larry Ng
NRIC/Fin No.:

Describe Circumstances of the Accident.

On 21.08.2020, at about 2330hrs, I was driving my Comfort taxi, SHA5789A, on the

Lane 2 along the KPE towards the city with no pax.

Somewhere after the Airport Rd exit, I suddenly felt a big impact from my right.

I then filtered left and stopped on the shoulder.

I went out and found out that a private car, B, had hit my taxi right rear side.

After that, my taxi lost control and my taxi right front was damaged too.

The male driver then came over and apologised to me.

Traffic was light. The police came and took away my taxi video camera SD card.

After that, the policeman asked me where was the other driver. I could not see him around. He may have left the scene.

After the accident, I felt pain in my back, both arms and discomfort in my neck. Will consult a doctor.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO. 199303821R

Policyholder's Signature/Date &
Time

Driver's Signature (If driver is not the policyholder)/Date
& Time

1000w

Larry Ng

Witnessed by Reporting
Centre Personnel