

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4445T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER CTR MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER LWR MOULDING	CRACKED	155.00	155.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	SMARTKEY ANTENNA	CRACKED	40.50	40.50
	LESS 20% DISCOUNT		-265.93	-225.63
			1,063.72	902.52
<u>NETT ITEMS</u>				
1	REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
1	NO PLATE (S) W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT CHARGE.		250.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
			720.00	550.00
GRAND TOTAL			2,045.22	1,714.02
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,714.02

Report Ref No. NS/INC20008960/T1sf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.