

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3465G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER UNDER CENTRE COVER	TO REPAIR SEE LABOUR	225.00	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-141.28	-96.28
			565.12	385.12
	SPECIAL NETT ITEMS			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	FENDER ADVERTISEMENT LOGO (SN)	NECESSARY	200.00	200.00
1	BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
			300.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER UNDER CENTRE COVER.		400.00	280.00
	SPRAY PAINTING.		400.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
			850.00	480.00
	GRAND TOTAL		1,715.12	1,165.12

RECOMMENDED COST OF LUMP SUM REPAIRS		950.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC20008963/T1sf3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.