

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Aug 2020		25 Aug 2020 14:46 Edit Adj Rpt	S\$6,100.00 Edit Estimates	S\$6,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured: JUMARI BIN SAMAHON , Co. Reg. No.: S1619008Z				
Main Claimant: LUMENS AUTO PTE LTD , Co. Reg. No.: 201426961K				
Vehicle Reg. No.: SMK7183Y		Date of Loss: 22/08/2020 16:00 - :59 [16 Months From LTA Reg Date (Man Yr)]		
Claim Type: TP / SNM20D203020/C02/TOHHS		Policy/Cover Note No.: DMPCSN30814219000 (Comprehensive) Coverage: 08/11/2019 - 02/02/2021		
Vehicle Reg. No. (Insured): SMN9750G		Policy No. (Claimant): Excess: S\$750.00		
Repairer: My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:				
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/09/2020]				
Adj Asg. Remarks: Advised by Huqin of My Car Consultant that Mr Steve of LKK Auto Consultants P L has already surveyed third party vehicle prior to notification from us. Please let us have your report & bill for services rendered.				
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS ☐				
View All Search Tasks Create New Task Complete				
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

***SMK7183Y (SNM20D203020/C02/TOHHS)
[SMN9750G]**

**TP
LUMENS AUTO PTE LTD
Aug 22 2020 4:00PM
[JUMARI BIN SAMAHON]
My Car Consultant Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/09/20 16:50	Adjuster Immediate Advice	 Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/08/20 21:55	General View	 Load JPG	☒
2	25/08/20 21:55	General View	 Load JPG	☒
3	25/08/20 21:55	General View	 Load JPG	☒
4	25/08/20 21:55	Odometer Reading	 Load JPG	☒
5	25/08/20 21:55	Chassis Number	 Load JPG	☒
6	25/08/20 21:55	General View	 Load JPG	☒
7	25/08/20 21:55	General View	 Load JPG	☒
8	25/08/20 21:55	General View	 Load JPG	☒
9	25/08/20 21:55	General View	 Load JPG	☒
10	25/08/20 21:55	General View	 Load JPG	☒
11	25/08/20 21:55	General View	 Load JPG	☒
12	25/08/20 21:55	General View	 Load JPG	☒
13	25/08/20 21:55	General View	 Load JPG	☒
14	25/08/20 21:55	General View	 Load JPG	☒
15	25/08/20 21:55	General View	 Load JPG	☒
16	25/08/20 21:55	General View	 Load JPG	☒
17	25/08/20 21:55	General View	 Load JPG	☒
18	25/08/20 21:55	General View	 Load JPG	☒
19	25/08/20 21:55	General View	 Load JPG	☒
20	25/08/20 21:55	General View	 Load JPG	☒
21	25/08/20 21:55	General View	 Load JPG	☒
22	25/08/20 21:55	General View	 Load JPG	☒
23	25/08/20 21:55	General View	 Load JPG	☒
24	25/08/20 21:55	General View	 Load JPG	☒
25	25/08/20 21:55	General View	 Load JPG	☒
26	25/08/20 21:55	General View	 Load JPG	☒
27	25/08/20 21:55	General View	 Load JPG	☒
28	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
29	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
30	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
31	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
32	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
33	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
34	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
35	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
36	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒
37	25/08/20 21:55	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
39	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
40	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
41	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
42	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
43	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
44	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
45	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
46	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
47	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
48	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
49	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
50	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
51	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
52	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
53	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
54	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
55	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
56	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
57	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
58	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
59	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
60	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
61	25/08/20 21:55	Photographs of Damaged Parts		Load JPG ☒
62	02/09/20 18:31	Photo After Spray		Load JPG ☒
63	02/09/20 18:31	Photo After Spray		Load JPG ☒
64	02/09/20 18:31	Photo After Spray		Load JPG ☒
65	02/09/20 18:31	Photo After Spray		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	25/08/20 12:01	REPORT OF SMN9750G		Load PDF
2	25/08/20 12:02	REPORT OF SMK7183Y		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/09/20 13:47	SUPPLEMENTARY		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20008969/ESF3S2**Date:** 08/09/2020**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30814219000

Claimant Vehicle No : SMK7183Y**Insured Vehicle No :** SMN9750G

Date of Loss: 22/08/2020

Nature of Claim: TP

Claim No: SNM20D203020/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK7183Y**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 2ZR0D15512

Reg. Date: 22/04/2019 (Man. Year: 2019)

Chassis No: JTDZS3EU60J038809

Colour: Red

Odometer: 181829 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,529.52	5,751.57	6,777.95	54.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,900.00	2,130.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,559.52	7,651.57	8,907.95	53.79
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	16,559.52	6,100.00	10,459.52	63.16

INSPECTION

Date of Assignment: 25/08/2020

Date Inspected: 25/08/2020 Inspected At:

My Car Consultant Pte Ltd (Ubi)
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Sep 2020)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK7183Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,211.00 FL	*929.00 FL
2	1		*TAILGATE LOCK	Bent	398.20 FL	*361.00 FL
3	1		*TAILGATE LOCK CATCH	Not Necessary	89.50 FL	*- FL
4	1		*TAILGATE LOCK SENSOR	Not Necessary	360.90 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Torn	212.00 FL	*196.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Broken	428.20 FL	*428.20 FL
7	1		*TAILGATE OUTER GARNISH	Broken	341.00 FL	*280.00 FL
8	1		*TAILGATE LOGO	Necessary	95.50 FL	*95.50 FL
9	1		*TAILGATE EMBLEM PRIUS	Necessary	89.40 FL	*50.00 FL
10	1		*TAILGATE EMBLEM HYBRID	Necessary	82.30 FL	*52.00 FL
11	1		*REAR BUMPER	Broken	658.00 FL	*523.90 FL
12	2		*REAR BUMPER SIDE RETAINER	Broken	224.00 FL	*224.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	350.50 FL	*350.50 FL
14	2		*REAR BUMPER BRACKET	Bent 1pc Only	228.00 FL	*114.00 FL
15	1		*REAR BUMPER CLIP	Cut	728.90 FL	*728.90 FL
16	2		*REAR BUMPER REFLECTOR	Broken 1pc Only	136.00 FL	*68.00 FL
17	2		*REAR NUMBER PLATE LAMP	Not Necessary	102.00 FL	*- FL
18	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	128.30 FL	*128.30 FL
19	1		*TAILLAMP	N/s Broken	1,024.00 FL	*512.00 FL
20	2		*REAR TAILLAMP INNER PANEL	Not Necessary	824.00 FL	*- FL
21	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	164.00 FL	*- FL
22	1		*REAR FLOOR PANEL	Repair	1,425.00 FL	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD	Broken	398.00 FL	*398.00 FL
24	1		*REAR EXHAUST PIPE	Not Necessary	1,251.00 FL	*- FL
25	1		*REAR KEYLESS SENSOR	Broken	169.50 FL	*169.50 FL
26	1		*REAR KEYLESS SENSOR WIRE HARNESS	Not Necessary	438.60 FL	*- FL
27	1		*REAR END PANEL	Dented	660.20 FL	*660.20 FL
28	1		*REAR END PANEL TOP GARNISH	Broken	225.10 FL	*225.10 FL
29	1		*REAR SPARE TYRE COMPARTMENT	Broken	694.30 FL	*396.00 FL
30	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
31	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*20.00 FS
32	1		*REAR TAILGATE OUTER GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
33	1		*REAR CAMERA	Not Necessary	350.00 FS	*- FS
34	1		*REAR REVERSE SENSOR	Broken	250.00 FS	*200.00 FS
35	1		*REAR FENDER INNER TRIM BOARD CLIPS LH	Not Necessary	80.00 FS	*- FS
36	1		*REAR FENDER INNER TRIM BOARD CLIPS RH	Not Necessary	80.00 FS	*- FS
37	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*20.00 FS
39	1		*REAR FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS
40	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
42	1		*REAR WINDSCREEN GLASS SOLAR FILM	Not Necessary	450.00 FS	*- FS
43	1		*REAR FLOOR UNDER COVER GARNISH	Deformed	312.00 FL	*312.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,219.40** **7,552.10**
- List Item Discount on L Items 20.00/25.00% (\$\$) 2,689.88 1,800.53

Report was unsubmitted during this print-out.

9/8/2020				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,529.52
						5,751.57
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING.	New	80.00	30.00
2	REMOVE AND RENEW REAR WIPER MOTOR.	New	150.00	30.00
3	TO REMOVE AND RENEW REVERSE SENSOR.	New	150.00	30.00
4	TO MOVE AND RENEW REAR REVERSE CAMERA.	New	150.00	30.00
5	TO REMOVE AND RENEW WINDSCREEN GLASS.	New	150.00	120.00
6	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY.	New	200.00	30.00
7	TO RESPRAY UNDERCOATING.	New	150.00	0.00
8	APPLY ANTI RUST ON AFFECTED AREAS.	New	200.00	30.00
9	SPRAY PAINTING ON AFFECTED AREAS.	New	1,400.00	800.00
10	PANEL BEATING ON AFFECTED AREAS.	New	1,400.00	800.00
Gross Labour Cost (\$\$)			4,030.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >