



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2006051  
INV Date 03/09/2020  
Reference CS/SMO20008981/Uvf3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. SJW 4859Z  
Insured Veh. SLS 3772T  
Claim No. CMTD2002491/IJH  
Policy No. D20MTPV01011049  
Accident Date 22/08/2020  
Inspection Date 26/08/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>450.00</b>
<b>GST (7%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>481.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20008981/Uvf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 03-09-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLS 3772T	Veh. Inspected	SJW 4859Z	
Policy No.	D20MTPV01011049	Coverage (\$)	0.00	
Claim No.	CMTD2002491/IJH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	25/08/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA CAMRY (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053BK4107056090	Colour	GREY	
Odometer	158923	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	6 mm	
L/H Front Tyre	215/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/08/2020	Inspection Date	26/08/2020	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 4859Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	798.00	622.10
1	REAR BUMPER REINFORCEMENT	DISTORTED	598.20	392.50
2	REAR BUMPER REFLECTOR @\$78.00	NOT NECESSARY	156.00	-
2	REAR BUMPER SIDE RETAINER @\$142.00	BENT	284.00	165.00
2	REAR BUMPER BRACE BRACKET @\$158.60	NO SUCH PARTS	317.20	-
1	BOOTLID	BUCKLED	1,879.20	1,145.20
1	BOOTLID CENTRE MOULDING	NOT NECESSARY	354.20	-
1	BOOTLID NUMBER PLATE GARNISH	CRACKED	389.00	389.00
1	BOOTLID LOCK	TWISTED	298.20	298.20
1	BOOTLID LOGO	NECESSARY	109.30	68.10
1	BOOTLID EMBLEM "CAMRY"	NECESSARY	89.20	75.10
1	BOOTLID EMBLEM "2.0"	NECESSARY	45.30	45.30
2	BOOTLID LAMP @\$521.00	SCRATCHED / CRACKED	1,042.00	760.00
1	BOOTLID WEATHERSTRIP	TWISTED	187.50	187.50
2	BOOTLID HINGES @\$159.00	TO REPAIR SEE LABOUR	318.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	254.00	-
1	BOOTLID SENSOR DETECTOR KEYLESS	NOT NECESSARY	321.00	-
2	TAILLAMP @\$798.00	CRACKED	1,596.00	970.40
2	REAR FENDER INNER TRIM @\$812.00	NOT NECESSARY	1,624.00	-
2	REAR FENDER COWLING @\$159.00	NOT NECESSARY	318.00	-
1	REAR END PANEL	BADLY DENTED	625.00	625.00
1	REAR END PANEL TOP GARNISH	DISTORTED	298.00	298.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,325.00	-
1	REAR FLOOR PANEL TOP BOARD	TORN	415.00	388.20
1	REAR FLOOR UNDERCOVER	NO SUCH PARTS	240.30	-
1	REAR CARGO BOX SPONGE	NOT NECESSARY	248.20	-
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	1,359.00	-
2	EXHAUST SILENCER MOUNTING @\$32.00	NOT NECESSARY	64.00	-

Report Ref No. CS/SMO20008981/Uvf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,888.20	-1,607.40
			11,664.60	4,822.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	300.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	50.00
1	BOOTLID SEALANT (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID CENTRE MOULDING CLIP (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET REAR END PANEL GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
1	FLOOR PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE WITH CASING (SN)(DENTED)	NOT CONSISTENT WITH THE IMPACT	50.00	-
			940.00	300.00
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	1,080.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF BOOTLID HINGES,REAR FLOOR PANEL AND EXHAUST SILENCER.		1,400.00	1,000.00
	REMOVE AND REFIT EXHAUST SYSTEM.	NOT NECESSARY	120.00	-
	REMOVE AND REFIT REAR SEAT,INNER TRIM SPEAKER.		200.00	80.00
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	REMOVE AND REFIT BOOTLID MECHANISM.		80.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR/CAMERA.		150.00	50.00
	APPLY ANTI RUST ON AFFECTED AREAS. }		200.00	60.00
	TO RESPRAY UNDERCOATING. }		150.00	-
	-		-	-
	-		-	-
	-		-	-
			3,980.00	2,360.00
<b>GRAND TOTAL</b>			<b>16,584.60</b>	<b>7,482.20</b>

Report Ref No. CS/SMO20008981/Uvf3n2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,900.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO20008981/Uvf3n2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.