

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008983/ATF3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNW00055212000	
Claimant Vehicle No : PC8491H	Insured Vehicle No : SMA8790R	
Date of Loss: 24/08/2020	Nature of Claim: TP	Claim No: SNM20D203023/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8491H		
Make & Model:	TOYOTA HIACE, 2.8 D COMMUTER GL (A)	Engine No:	1GD8427279
Reg. Date:	11/10/2019 (Man. Year: 2019)	Chassis No:	GDH2232001898
Colour:	White	Odometer:	36762 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,822.11	3,141.76	2,680.35	46.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,610.00	700.00	30.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,132.11	4,751.76	3,380.35	41.57
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	8,132.11	3,800.00	4,332.11	53.27
+ GST 7.00/7.00% (S\$)	569.25	266.00	303.25	53.27
Nett Amount (S\$)	8,701.36	4,066.00	4,635.36	53.27

INSPECTION

Date of Assignment:	25/08/2020	
Date Inspected:	26/08/2020	Inspected At: BLK 5 DEFU LANE 10#01-570
		Repairer: J-mart Motor Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8491H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,198.00 FL	*1,780.00 FL
2	1		*GL EMBLEM	Necessary	55.00 FL	*55.00 FL
3	1		*LOGO EMBLEM	Necessary	72.20 FL	*72.20 FL
4	1		*TAILGATE LOCK	Damaged	275.00 FL	*275.00 FL
5	1		*HIACE EMBLEM	Necessary	55.91 FL	*55.91 FL
6	1		*TAILGATE W/STRIP	Not Necessary	455.00 FL	*- FL
7	1		*REAR BUMPER	Deformed	575.10 FL	*575.10 FL
8	2		*REAR BUMPER RETAINER	Necessary	100.00 FL	*100.00 FL
9	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
10	4		*REAR BUMPER BRACKET	Bent	120.00 FL	*100.00 FL
11	1		*END PANEL OUTER	Repair	850.00 FL	*- FL
12	1		*END PANEL INNER	Repair	980.80 FL	*- FL
13	1		*RH TAILLAMP	Cracked	300.80 FL	*300.80 FL
14	1		*RH APRON PANEL	Deformed	145.00 FL	*145.00 FL
15	1		*70KM/H STICKER	Necessary	25.00 FS	*25.00 FS
16	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
17	1		*RH TAILLAMP CHROME	Necessary	200.00 FS	*100.00 FS
18	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
19	1		*EXHAUST PIPE (LOCAL REPAIR)	Bent	637.50 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,375.31	4,014.01
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,553.20	872.25
Total Parts (\$\$)	5,822.11	3,141.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	WIRING	New	30.00	30.00
4	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
5	TRANSFER TAILGATE FITTING	New	80.00	80.00
6	REMOVE & REFIT EXHAUST PIPE	New	80.00	80.00
Gross Labour Cost (S\$)			2,310.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >